

FISA VALIDARE INVENTAR

R1014 - CIMPENI



DATE GENERALE STATIE

Cod statie	:	R1014	Data verificarii	:	
Nume statie	:	CIMPENI	Persoana care verifica	:	
Numar distribuitoare	:	2			
Numar echipamente Sistem masura rezervoare	:			7	
Numar echipamente Rezervoare / sisteme asociate	:			18	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 2 - Pompa 1/2

Cod echipament	:	RO_013077	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	683708	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	SK700	☐ Corect	

DISTRIBUITOR 2 DIN 2 - Pompa 3/4

Cod echipament	:	RO_013078	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	683709	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	SK700	☐ Corect	

FISA VALIDARE INVENTAR

R1014 - CIMPENI



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013080	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	T05258578329001	☐ Corect	_____
Producator	:	Veeder-Root 450Plus_	☐ Corect	_____
Tip echipament	:	Veeder-Root 450Plus	☐ Corect	_____
Data fabricatiei	:	03.07.2019	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013081	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R1/1 Senzori R1	☐ Corect	_____
Data fabricatiei	:	03.07.2019	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013082	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R1/2 Senzori R2	☐ Corect	_____
Data fabricatiei	:	03.07.2019	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013083	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R2/1 Senzori R3/1	☐ Corect	_____
Data fabricatiei	:	03.07.2019	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013084	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R2/2 Senzori R3/2	☐ Corect	_____
Data fabricatiei	:	03.07.2019	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1014 - CIMPENI



VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_013085	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	03.07.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_013086	☐ Corect
Serie echipament	:	323	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	03.07.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1014 - CIMPENI



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 4

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:		☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013087	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	03.07.2019	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	03.07.2019	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	03.07.2019	☐ Corect	

REZERVOR 2 DIN 4

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013090	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	03.07.2019	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	03.07.2019	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	03.07.2019	☐ Corect	

REZERVOR 3 DIN 4

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013093	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	03.07.2019	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	03.07.2019	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	03.07.2019	☐ Corect	

REZERVOR 4 DIN 4

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013096	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	03.07.2019	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	03.07.2019	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	03.07.2019	☐ Corect	

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 2

FISA VALIDARE INVENTAR

R1014 - CIMPENI



Sistem de detectie scurgeri : Rezervor 1 bicompartimentat ☐ Corect
Cod echipament : RO_013099 ☐ Corect
Serie echipament : ☐ Corect
Producator : SGB ☐ Corect
Data fabricatiei : 03.07.2019 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 2

Sistem de detectie scurgeri : Rezervor 2 bicompartimentat ☐ Corect
Cod echipament : RO_013100 ☐ Corect
Serie echipament : ☐ Corect
Producator : SGB ☐ Corect
Data fabricatiei : 03.07.2019 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____