

FISA VALIDARE INVENTAR

R1024 - BUCHIN



DATE GENERALE STATIE

Cod statie	: R1024	Data verificarii	:
Nume statie	: BUCHIN	Persoana care verifica	:
Numar distribuitoare	: 4		
Numar echipamente Sistem masura rezervoare	:	8	
Numar echipamente Rezervoare / sisteme asociate	:	20	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 4 - Pompa 5/6

Cod echipament	: RO_004992	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 683245	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	: HS 1-2	☐ Corect	
Numar dispenser	: Pompa 5/6	☐ Corect	
Data fabricatiei	: 01.01.2018	☐ Corect	
Numar produse	: 1	☐ Corect	
Debit	: 130 l/min	☐ Corect	Observatii:
Numar pistoale	: 2	☐ Corect	
Calculator pompa	: SK700	☐ Corect	

DISTRIBUITOR 2 DIN 4 - Pompa 7/8

Cod echipament	: RO_004993	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 684464	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root_SK700-2/ADBLUE	☐ Corect	
Tip echipament	: MPD 1/2 (Container Ad Blue - OMV)	☐ Corect	
Numar dispenser	: Pompa 7/8	☐ Corect	
Data fabricatiei	: 01.01.2018	☐ Corect	
Numar produse	: 1	☐ Corect	
Debit	: 80 l/min	☐ Corect	Observatii:
Numar pistoale	: 2	☐ Corect	
Calculator pompa	: SK700	☐ Corect	

DISTRIBUITOR 3 DIN 4 - Pompa 3/4

Cod echipament	: RO_004994	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 683246	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 3/4	☐ Corect	
Data fabricatiei	: 01.01.2018	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: SK700	☐ Corect	

DISTRIBUITOR 4 DIN 4 - Pompa 1/2

Cod echipament	: RO_004995	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 683247	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 1/2	☐ Corect	
Data fabricatiei	: 01.01.2018	☐ Corect	
Numar produse	: 4	☐ Corect	

FISA VALIDARE INVENTAR

R1024 - BUCHIN



Debit : 40 l/min
Numar pistoale : 8
Calculator pompa : SK700

☐ Corect
☐ Corect
☐ Corect

Observatii:

FISA VALIDARE INVENTAR

R1024 - BUCHIN



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_004997	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	TLS 450 PLUS	☐ Corect	
Tip echipament	:	Veeder-Root 450		
		Veeder-Root 350R	☐ Corect	
Data fabricatiei	:	19.12.2018	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_004998	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/1	☐ Corect	
Data fabricatiei	:	19.12.2018	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_004999	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/2	☐ Corect	
Data fabricatiei	:	19.12.2018	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_005000	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1	☐ Corect	
Data fabricatiei	:	19.12.2018	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_005001	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/2	☐ Corect	
Data fabricatiei	:	19.12.2018	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1024 - BUCHIN



SONDA NIVEL 5 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_005002	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3	☐ Corect
Data fabricatiei	:	19.12.2018	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_005003	☐ Corect
Serie echipament	:	295	☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	19.12.2018	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_005004	☐ Corect
Serie echipament	:	519	☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica 5m	☐ Corect
Data fabricatiei	:	19.12.2018	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1024 - BUCHIN



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 5

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_005005	☐ Corect	
Serie echipament	:	952/2018	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	19.12.2018	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	19.12.2018	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	19.12.2018	☐ Corect	

REZERVOR 2 DIN 5

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_005008	☐ Corect	
Serie echipament	:	952/2018	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	19.12.2018	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	19.12.2018	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	19.12.2018	☐ Corect	

REZERVOR 3 DIN 5

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_005011	☐ Corect	
Serie echipament	:	953/2018	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	19.12.2018	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	19.12.2018	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	19.12.2018	☐ Corect	

REZERVOR 4 DIN 5

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Extra 99	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_005014	☐ Corect	
Serie echipament	:	953/2018	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	19.12.2018	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	19.12.2018	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	19.12.2018	☐ Corect	

REZERVOR 5 DIN 5

Rezervor	:	R3 monocompartimentat Adblue/Container	☐ Corect	☐ Datele sunt
corecte ☐ Necesita modificari				
Produs	:	R3 Adblue	☐ Corect	Valori corectate / informatii de pe placuta:

FISA VALIDARE INVENTAR

R1024 - BUCHIN



Cod echipament	:	RO_005017	☐ Corect
Serie echipament	:	151227961	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	13.12.2018	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:		☐ Corect

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 2

Sistem de detectie scurgeri	:	Rezervor 1 bicompartimentat	☐ Corect
Cod echipament	:	RO_005019	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	19.12.2018	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 2

Sistem de detectie scurgeri	:	Rezervor 2 bicompartimentat	☐ Corect
Cod echipament	:	RO_005020	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	19.12.2018	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____