

FISA VALIDARE INVENTAR

R1039 - Arad 6 Ringroad



DATE GENERALE STATIE

Cod statie	:	R1039	Data verificarii	:	
Nume statie	:	Arad 6 Ringroad	Persoana care verifica	:	
Numar distribuitoare	:	8			
Numar echipamente Sistem masura rezervoare	:			9	
Numar echipamente Rezervoare / sisteme asociate	:			29	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 8 - Pompa 7/8

Cod echipament	:	RO_240483	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	684635	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2/	☐ Corect	
Tip echipament	:	HS 1-2	☐ Corect	
Numar dispenser	:	Pompa 7/8	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	120 l/min	☐ Corect	Observatii:
Numar pistoale	:	1	☐ Corect	
Calculator pompa	:		☐ Corect	

DISTRIBUITOR 2 DIN 8 - Pompa 9

Cod echipament	:	RO_240484	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	684639	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2/	☐ Corect	
Tip echipament	:	HS 1-1	☐ Corect	
Numar dispenser	:	Pompa 9	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	120 l/min	☐ Corect	Observatii:
Numar pistoale	:	1	☐ Corect	
Calculator pompa	:		☐ Corect	

DISTRIBUITOR 3 DIN 8 - Pompa 9 satelit

Cod echipament	:	RO_240485	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	684638	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2/	☐ Corect	
Tip echipament	:	Pompa satelit	☐ Corect	
Numar dispenser	:	Pompa 9 satelit	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	120 l/min	☐ Corect	Observatii:
Numar pistoale	:	1	☐ Corect	
Calculator pompa	:		☐ Corect	

DISTRIBUITOR 4 DIN 8 - Pompa 11/12 Container Ad Blue

Cod echipament	:	RO_240486	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	684839	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2/ADBLUE	☐ Corect	
Tip echipament	:	MPD 1/2 (Ad Blue - OMV) Container	☐ Corect	
Numar dispenser	:	Pompa 11/12 Container Ad Blue	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	
Numar produse	:	1	☐ Corect	

FISA VALIDARE INVENTAR

R1039 - Arad 6 Ringroad



Debit	:	40 l/min	☐ Corect
Numar pistoale	:	2	☐ Corect
Calculator pompa	:		☐ Corect

Observatii:

DISTRIBUITOR 5 DIN 8 - Pompa 13/14 Container Ad Blue

Cod echipament	:	RO_240487	☐ Corect
Serie echipament	:	684850	☐ Corect
Producator	:	Gilbarco Veeder-Root_SK700-2/ADBLUE	

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

☐ Corect

Tip echipament	:	MPD 1/2 (Ad Blue - OMV) Container	☐ Corect
Numar dispenser	:	Pompa 13/14 Container Ad Blue	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect
Numar produse	:	1	☐ Corect
Debit	:	40 l/min	☐ Corect
Numar pistoale	:	2	☐ Corect
Calculator pompa	:		☐ Corect

Observatii:

DISTRIBUITOR 6 DIN 8 - Pompa 1/2

Cod echipament	:	RO_240488	☐ Corect
Serie echipament	:	684625	☐ Corect
Producator	:	Gilbarco Veeder-Root_SK700-2/	☐ Corect
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect
Numar dispenser	:	Pompa 1/2	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect
Numar produse	:	4	☐ Corect
Debit	:	40 l/min	☐ Corect
Numar pistoale	:	8	☐ Corect
Calculator pompa	:		☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DISTRIBUITOR 7 DIN 8 - Pompa 3/4

Cod echipament	:	RO_240489	☐ Corect
Serie echipament	:	684626	☐ Corect
Producator	:	Gilbarco Veeder-Root_SK700-2/	☐ Corect
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect
Numar dispenser	:	Pompa 3/4	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect
Numar produse	:	4	☐ Corect
Debit	:	40 l/min	☐ Corect
Numar pistoale	:	8	☐ Corect
Calculator pompa	:		☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DISTRIBUITOR 8 DIN 8 - Pompa 5/6

Cod echipament	:	RO_240490	☐ Corect
Serie echipament	:	684627	☐ Corect
Producator	:	Gilbarco Veeder-Root_SK700-2/	☐ Corect
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect
Numar dispenser	:	Pompa 5/6	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect
Numar produse	:	4	☐ Corect
Debit	:	40 l/min	☐ Corect
Numar pistoale	:	8	☐ Corect
Calculator pompa	:		☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1039 - Arad 6 Ringroad



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_240492	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 450 Plus	☐ Corect	
Tip echipament	:	Veeder-Root 450 Plus		
		Veeder-Root 350R	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_240493	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_240494	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_240495	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R3/1	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_240496	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R3/2	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1039 - Arad 6 Ringroad



SONDA NIVEL 5 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_240497	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R4	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 6 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_240498	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R5	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_240499	☐ Corect
Serie echipament	:	426	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_240500	☐ Corect
Serie echipament	:	213	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica 5m	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1039 - Arad 6 Ringroad



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 7

Rezervor	:	R1 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_240501	☐ Corect	
Serie echipament	:	19127	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	

REZERVOR 2 DIN 7

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_240504	☐ Corect	
Serie echipament	:	19128	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	

REZERVOR 3 DIN 7

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_240507	☐ Corect	
Serie echipament	:	19128	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	

REZERVOR 4 DIN 7

Rezervor	:	R3/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3/1 MM100	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_240510	☐ Corect	
Serie echipament	:	19129	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	

REZERVOR 5 DIN 7

Rezervor	:	R3/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3/2 Extra 99	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_240513	☐ Corect	

FISA VALIDARE INVENTAR

R1039 - Arad 6 Ringroad



Serie echipament	:	19129	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect
Capac Rezervor	:	unknown	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect

Observatii:

REZERVOR 6 DIN 7

Rezervor	:	R4 monocompartmentat Adblue/Container	☐ Corect
corecte ☐ Necesita modificari			☐ Datele sunt
Produs	:	R4 Adblue	☐ Corect
Cod echipament	:	RO_240516	☐ Corect
Serie echipament	:	FS	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect
Capac Rezervor	:	unknown	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect

Valori corectate / informatii de pe placuta:

Observatii:

REZERVOR 7 DIN 7

Rezervor	:	R5 monocompartmentat Adblue/Container	☐ Corect
corecte ☐ Necesita modificari			☐ Datele sunt
Produs	:		☐ Corect
Cod echipament	:	RO_240518	☐ Corect
Serie echipament	:	FS	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect
Capac Rezervor	:	unknown	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect

Valori corectate / informatii de pe placuta:

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 3

Sistem de detectie scurgeri	:	Rezervor 1 monocompartmentat	☐ Corect
Cod echipament	:	RO_240520	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 3

Sistem de detectie scurgeri	:	Rezervor 2 bicompartimentat	☐ Corect
Cod echipament	:	RO_240521	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 3

Sistem de detectie scurgeri	:	Rezervor 3 bicompartimentat	☐ Corect
Cod echipament	:	RO_240522	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1039 - Arad 6 Ringroad



VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____