

FISA VALIDARE INVENTAR

R1062 - OMV Zalau Ring Road



DATE GENERALE STATIE

Cod statie	:	R1062	Data verificarii	:	
Nume statie	:	OMV Zalau Ring Road	Persoana care verifica	:	
Numar distribuitoare	:	8			
Numar echipamente Sistem masura rezervoare	:			9	
Numar echipamente Rezervoare / sisteme asociate	:			28	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 8 - Pompa 7/8

Cod echipament	:	RO_237854	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	929422	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	:	HS 1-2	☐ Corect	
Numar dispenser	:	Pompa 7/8	☐ Corect	
Data fabricatiei	:	01.01.2021	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	130 l/min	☐ Corect	Observatii:
Numar pistoale	:	2	☐ Corect	
Calculator pompa	:	Apollo	☐ Corect	

DISTRIBUITOR 2 DIN 8 - Pompa 15/16

Cod echipament	:	RO_237855	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	929423	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2/ADBLUE	☐ Corect	
Tip echipament	:	MPD 1/2 (Ad Blue - OMV)	☐ Corect	
Numar dispenser	:	Pompa 15/16	☐ Corect	
Data fabricatiei	:	01.01.2021	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	80 l/min	☐ Corect	Observatii:
Numar pistoale	:	2	☐ Corect	
Calculator pompa	:	Apollo	☐ Corect	

DISTRIBUITOR 3 DIN 8 - Pompa 13/14

Cod echipament	:	RO_237856	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	929425	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2/ADBLUE	☐ Corect	
Tip echipament	:	MPD 1/2 (Ad Blue - OMV)	☐ Corect	
Numar dispenser	:	Pompa 13/14	☐ Corect	
Data fabricatiei	:	01.01.2021	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	80 l/min	☐ Corect	Observatii:
Numar pistoale	:	2	☐ Corect	
Calculator pompa	:	Apollo	☐ Corect	

DISTRIBUITOR 4 DIN 8 - Pompa 11/12

Cod echipament	:	RO_237857	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	929426	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2/ADBLUE	☐ Corect	
Tip echipament	:	MPD 1/2 (Ad Blue - OMV)	☐ Corect	
Numar dispenser	:	Pompa 11/12	☐ Corect	

FISA VALIDARE INVENTAR

R1062 - OMV Zalau Ring Road



Data fabricatiei	:	01.01.2021	☐ Corect
Numar produse	:	1	☐ Corect
Debit	:	80 l/min	☐ Corect
Numar pistoale	:	2	☐ Corect
Calculator pompa	:	Apollo	☐ Corect

Observatii:

DISTRIBUITOR 5 DIN 8 - Pompa 9/10

Cod echipament	:	RO_237858	☐ Corect
Serie echipament	:	929424	☐ Corect
Producator	:	Gilbarco Veeder-Root_SK700-2/ADBLUE	

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

☐ Corect

Tip echipament	:	MPD 1/2 (Ad Blue - OMV)	☐ Corect
Numar dispenser	:	Pompa 9/10	☐ Corect
Data fabricatiei	:	01.01.2021	☐ Corect
Numar produse	:	1	☐ Corect
Debit	:	80 l/min	☐ Corect
Numar pistoale	:	2	☐ Corect
Calculator pompa	:	Apollo	☐ Corect

Observatii:

DISTRIBUITOR 6 DIN 8 - Pompa 1/2

Cod echipament	:	RO_237859	☐ Corect
Serie echipament	:	929419	☐ Corect
Producator	:	Gilbarco Veeder-Root_SK700-2	☐ Corect
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect
Numar dispenser	:	Pompa 1/2	☐ Corect
Data fabricatiei	:	01.01.2021	☐ Corect
Numar produse	:	4	☐ Corect
Debit	:	40 l/min	☐ Corect
Numar pistoale	:	8	☐ Corect
Calculator pompa	:	Apollo	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DISTRIBUITOR 7 DIN 8 - Pompa 3/4

Cod echipament	:	RO_237860	☐ Corect
Serie echipament	:	929420	☐ Corect
Producator	:	Gilbarco Veeder-Root_SK700-2	☐ Corect
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect
Numar dispenser	:	Pompa 3/4	☐ Corect
Data fabricatiei	:	01.01.2021	☐ Corect
Numar produse	:	4	☐ Corect
Debit	:	40 l/min	☐ Corect
Numar pistoale	:	8	☐ Corect
Calculator pompa	:	Apollo	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DISTRIBUITOR 8 DIN 8 - Pompa 5/6

Cod echipament	:	RO_237861	☐ Corect
Serie echipament	:	929421	☐ Corect
Producator	:	Gilbarco Veeder-Root_SK700-2	☐ Corect
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect
Numar dispenser	:	Pompa 5/6	☐ Corect
Data fabricatiei	:	01.01.2021	☐ Corect
Numar produse	:	4	☐ Corect
Debit	:	40 l/min	☐ Corect
Numar pistoale	:	8	☐ Corect
Calculator pompa	:	Apollo	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1062 - OMV Zalau Ring Road



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_237862	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	211070	☐ Corect	_____
Producator	:	MAGLINK-LX_	☐ Corect	_____
Tip echipament	:	ProGauge	☐ Corect	_____
Data fabricatiei	:	01.01.2022	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_237863	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	MAGLINK-LX_	☐ Corect	_____
Tip echipament	:	Sonda R1/1	☐ Corect	_____
Data fabricatiei	:	01.01.2022	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_237864	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	MAGLINK-LX_	☐ Corect	_____
Tip echipament	:	Sonda R1/2	☐ Corect	_____
Data fabricatiei	:	01.01.2022	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_237865	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	MAGLINK-LX_	☐ Corect	_____
Tip echipament	:	Sonda R2/1	☐ Corect	_____
Data fabricatiei	:	01.01.2022	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_237866	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	MAGLINK-LX_	☐ Corect	_____
Tip echipament	:	Sonda R2/2	☐ Corect	_____
Data fabricatiei	:	01.01.2022	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1062 - OMV Zalau Ring Road



SONDA NIVEL 5 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_237867	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	MAGLINK-LX_	☐ Corect
Tip echipament	:	Sonda R3	☐ Corect
Data fabricatiei	:	01.01.2022	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 6 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_237868	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	MAGLINK-LX_	☐ Corect
Tip echipament	:	Sonda R4	☐ Corect
Data fabricatiei	:	01.01.2022	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_237869	☐ Corect
Serie echipament	:	46	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	01.01.2022	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_237870	☐ Corect
Serie echipament	:	653	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica 5m	☐ Corect
Data fabricatiei	:	01.01.2022	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1062 - OMV Zalau Ring Road



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 6

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 OMV Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_237871	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	

REZERVOR 2 DIN 6

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 OMV maxx95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_237874	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	

REZERVOR 3 DIN 6

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 OMV MaxxDiesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_237877	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	

REZERVOR 4 DIN 6

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 OMV Max100Plus	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_237880	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	

REZERVOR 5 DIN 6

Rezervor	:	R3 monocompartimentat OMV Diesel	☐ Corect	☐ Datele sunt
corecte				☐ Necesita modificari

FISA VALIDARE INVENTAR

R1062 - OMV Zalau Ring Road



Produs	:	R3 monocompartmentat OMV Diesel	☐ Corect	Valori corectate /
informatii de pe placuta:				
Cod echipament	:	RO_237883	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	

REZERVOR 6 DIN 6

Rezervor	:	R4 monocompartmentat Adblue	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R4 Adblue	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_237886	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	Observatii:
Capac Rezervor	:	Tank shaft incl. Covers (not for AdBlue container)	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 4

Sistem de detectie scurgeri	:	Rezervor 1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_237889	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	SGB	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 4

Sistem de detectie scurgeri	:	Rezervor 2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_237890	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	SGB	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 4

Sistem de detectie scurgeri	:	Rezervor 3 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_237891	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	SGB	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	Observatii:

SISTEM DE DETECTIE SCURGERI 4 DIN 4

Sistem de detectie scurgeri	:	Rezervor 4 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_237892	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	SGB	☐ Corect	

FISA VALIDARE INVENTAR

R1062 - OMV Zalau Ring Road



Data fabricatiei : 01.01.2022

[] Corect

Observatii:

VERIFICARE FINALA

Nume: _____

Funcție: _____

Data: _____

Semnatura: _____