

FISA VALIDARE INVENTAR

R1077 - 1 Cluj



FISA DE VALIDARE INVENTAR DISTRIBUITOARE

Cod statie : R1077 Data verificarii :
Nume statie : 1 Cluj Persoana care verifica :
Numar distribuitoare : 3

DISTRIBUITOR 1 DIN 3 - Pompa 1/2

Cod echipament	: RO_226199	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 306356	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: DRESSER WAYNE PIGNONE	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 1/2	☐ Corect	
Data fabricatiei	: 01.01.2005	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: DPX-F2	☐ Corect	

DISTRIBUITOR 2 DIN 3 - Pompa 3/4

Cod echipament	: RO_226200	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 307471	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: DRESSER WAYNE PIGNONE	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 3/4	☐ Corect	
Data fabricatiei	: 01.01.2005	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: DPX-F2	☐ Corect	

DISTRIBUITOR 3 DIN 3 - Pompa 5/6

Cod echipament	: RO_226201	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 307796	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: DRESSER WAYNE PIGNONE	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 5/6	☐ Corect	
Data fabricatiei	: 01.01.2005	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: DPX-F2	☐ Corect	

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____