

FISA VALIDARE INVENTAR

R1083 - 8 Cluj



DATE GENERALE STATIE

Cod statie	:	R1083	Data verificarii	:	
Nume statie	:	8 Cluj	Persoana care verifica	:	
Numar distribuitoare	:	3			
Numar echipamente Sistem masura rezervoare	:			5	
Numar echipamente Rezervoare / sisteme asociate	:			10	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 3 - Pompa 1/2

Cod echipament	:	RO_226074	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	1321237	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantium 510	☐ Corect	
Tip echipament	:	MPD 2/4 VR 1/2	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2013	☐ Corect	
Numar produse	:	2	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	4	☐ Corect	
Calculator pompa	:	TQC	☐ Corect	

DISTRIBUITOR 2 DIN 3 - Pompa 3/4

Cod echipament	:	RO_226075	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	1321238	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantium 510	☐ Corect	
Tip echipament	:	MPD 2/4 VR 1/2	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2013	☐ Corect	
Numar produse	:	2	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	4	☐ Corect	
Calculator pompa	:	TQC	☐ Corect	

DISTRIBUITOR 3 DIN 3 - Pompa 5/6

Cod echipament	:	RO_226076	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	1321239	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantium 510	☐ Corect	
Tip echipament	:	MPD 2/4 VR 1/2	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	01.01.2013	☐ Corect	
Numar produse	:	2	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	4	☐ Corect	
Calculator pompa	:	TQC	☐ Corect	

FISA VALIDARE INVENTAR

R1083 - 8 Cluj



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_226078	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	ELECTRONIC_	☐ Corect	
Tip echipament	:	ELECTRONIC OPTILEVEL		
		Optilevel C104M	☐ Corect	
Data fabricatiei	:	01.04.2009	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 2

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_226083	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R5	☐ Corect	
Data fabricatiei	:	01.04.2009	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 2

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_226084	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R6	☐ Corect	
Data fabricatiei	:	01.04.2009	☐ Corect	Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_226085	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	2	☐ Corect	
Producator	:	AMPLO SA	☐ Corect	
Tip echipament	:	Vas etalon	☐ Corect	
Data fabricatiei	:	01.01.2008	☐ Corect	Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_235798	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	738	☐ Corect	
Producator	:	Mecaf_	☐ Corect	
Tip echipament	:	Rigla metalica Rigla 4m	☐ Corect	
Data fabricatiei	:	01.01.2020	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1083 - 8 Cluj



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 2

Rezervor	:	R5 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R5 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_226099	☐ Corect	
Serie echipament	:	62A	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.1995	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.01.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.01.2001	☐ Corect	

REZERVOR 2 DIN 2

Rezervor	:	R6 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R6 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_226102	☐ Corect	
Serie echipament	:	62B	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.1995	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.01.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.01.2001	☐ Corect	

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 2

Sistem de detectie scurgeri	:	Rezervor 5 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_226105	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	AFRSIO	☐ Corect	
Data fabricatiei	:	01.01.2001	☐ Corect	Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 2

Sistem de detectie scurgeri	:	Rezervor 6 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_226106	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	AFRISO	☐ Corect	
Data fabricatiei	:	01.01.2001	☐ Corect	Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____