

FISA VALIDARE INVENTAR

R1491 - 5 Deva



DATE GENERALE STATIE

Cod statie	:	R1491	Data verificarii	:	
Nume statie	:	5 Deva	Persoana care verifica	:	
Numar distribuitoare	:	3			
Numar echipamente Sistem masura rezervoare	:			8	
Numar echipamente Rezervoare / sisteme asociate	:			22	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 3 - Pompa 3/4

Cod echipament	:	RO_015785	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	313780	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Dresser Waine Pignone_DPX	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2006	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	SK700	☐ Corect	

DISTRIBUITOR 2 DIN 3 - Pompa 5/6

Cod echipament	:	RO_015786	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	400595	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Dresser Waine Pignone_DPX	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4 (DM)	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	01.01.2006	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:		☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	SK700	☐ Corect	

DISTRIBUITOR 3 DIN 3 - Pompa 1/2

Cod echipament	:	RO_015787	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	313767	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Dresser Waine Pignone_DPX	☐ Corect	
Tip echipament	:	MPD 4/8 VR 3/6	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2006	☐ Corect	
Numar produse	:	3	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	SK700	☐ Corect	

FISA VALIDARE INVENTAR

R1491 - 5 Deva



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_015789	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	260043	☐ Corect	
Producator	:	ELECTRONIC	☐ Corect	
Tip echipament	:	ELECTRONIC OPTILEVEL		
		Optilevel C104M	☐ Corect	
Data fabricatiei	:	20.12.2006	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_015790	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root	☐ Corect	
Tip echipament	:	Sonda R1/1	☐ Corect	
Data fabricatiei	:	20.12.2006	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_015791	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root	☐ Corect	
Tip echipament	:	Sonda R1/2	☐ Corect	
Data fabricatiei	:	20.12.2006	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_015792	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root	☐ Corect	
Tip echipament	:	Sonda R2/1	☐ Corect	
Data fabricatiei	:	20.12.2006	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_015793	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root	☐ Corect	
Tip echipament	:	Sonda R2/2	☐ Corect	
Data fabricatiei	:	20.12.2006	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1491 - 5 Deva



SONDA NIVEL 5 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_015794	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2/3	☐ Corect
Data fabricatiei	:	20.12.2006	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_015795	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	20.12.2006	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_015796	☐ Corect
Serie echipament	:	654	☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	20.12.2006	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1491 - 5 Deva



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 5

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_015797	☐ Corect	
Serie echipament	:	464	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	20.12.2006	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	20.12.2006	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	20.12.2006	☐ Corect	

REZERVOR 2 DIN 5

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_015800	☐ Corect	
Serie echipament	:	464	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	20.12.2006	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	20.12.2006	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	20.12.2006	☐ Corect	

REZERVOR 3 DIN 5

Rezervor	:	R2/1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_015803	☐ Corect	
Serie echipament	:	470	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	20.12.2006	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	20.12.2006	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	20.12.2006	☐ Corect	

REZERVOR 4 DIN 5

Rezervor	:	R2/2 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_015806	☐ Corect	
Serie echipament	:	470	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	20.12.2006	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	20.12.2006	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	20.12.2006	☐ Corect	

REZERVOR 5 DIN 5

Rezervor	:	R2/3 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/3 Extra 99	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_015809	☐ Corect	

FISA VALIDARE INVENTAR

R1491 - 5 Deva



Serie echipament	:	470	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	20.12.2006	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	20.12.2006	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	20.12.2006	☐ Corect

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 2

Sistem de detectie scurgeri	:	Rezervor 1 bicompartimentat	☐ Corect
Cod echipament	:	RO_015812	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	20.12.2006	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 2

Sistem de detectie scurgeri	:	Rezervor 2 tricompartimentat	☐ Corect
Cod echipament	:	RO_015813	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	20.12.2006	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____