

FISA VALIDARE INVENTAR

R1495 - 2 Hateg



DATE GENERALE STATIE

Cod statie	: R1495	Data verificarii	:
Nume statie	: 2 Hateg	Persoana care verifica	:
Numar distribuitoare	: 3		
Numar echipamente Sistem masura rezervoare	:	9	
Numar echipamente Rezervoare / sisteme asociate	:	27	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 3 - Pompa 5/6

Cod echipament	: RO_025244	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 701123	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root	☐ Corect	
Tip echipament	: HS 1-2	☐ Corect	
Numar dispenser	: Pompa 5/6	☐ Corect	
Data fabricatiei	: 01.01.2020	☐ Corect	
Numar produse	: 1	☐ Corect	
Debit	: 130 l/min	☐ Corect	Observatii:
Numar pistoale	: 2	☐ Corect	
Calculator pompa	: Tatsuno	☐ Corect	

DISTRIBUITOR 2 DIN 3 - Pompa 3/4

Cod echipament	: RO_025245	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 701091	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 3/4	☐ Corect	
Data fabricatiei	: 01.01.2020	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: Tatsuno	☐ Corect	

DISTRIBUITOR 3 DIN 3 - Pompa 1/2

Cod echipament	: RO_025246	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 701084	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root	☐ Corect	
Tip echipament	: MPD 4/8 VR 3/6	☐ Corect	
Numar dispenser	: Pompa 1/2	☐ Corect	
Data fabricatiei	: 01.01.2020	☐ Corect	
Numar produse	: 3	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: Tatsuno	☐ Corect	

FISA VALIDARE INVENTAR

R1495 - 2 Hateg



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_016037	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 450Plus_	☐ Corect	
Tip echipament	:	Veeder-Root 450Plus_	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_016038	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/1	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_016039	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/2	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_016040	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_016041	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/2	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1495 - 2 Hateg



SONDA NIVEL 5 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_016042	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3/1	☐ Corect
Data fabricatiei	:	16.08.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 6 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_016043	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3/2	☐ Corect
Data fabricatiei	:	16.08.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_016044	☐ Corect
Serie echipament	:	116/2008	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	18.04.2023	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_016045	☐ Corect
Serie echipament	:	476	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 4m	☐ Corect
Data fabricatiei	:	01.03.2003	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1495 - 2 Hateg



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 6

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_016046	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.03.2003	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.03.2003	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.03.2003	☐ Corect	

REZERVOR 2 DIN 6

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_016049	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.03.2003	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.03.2003	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.03.2003	☐ Corect	

REZERVOR 3 DIN 6

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_016052	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.03.2003	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.03.2003	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.03.2003	☐ Corect	

REZERVOR 4 DIN 6

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_016055	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.03.2003	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.03.2003	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.03.2003	☐ Corect	

REZERVOR 5 DIN 6

Rezervor	:	R3/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3/1 Extra 99	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_016058	☐ Corect	

FISA VALIDARE INVENTAR

R1495 - 2 Hateg



Serie echipament	:		☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.03.2003	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	01.03.2003	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	01.03.2003	☐ Corect

Observatii:

REZERVOR 6 DIN 6

Rezervor	:	R3/2 bicompartimentat	☐ Corect
Produs	:	R3/2 Diesel Std	☐ Corect
Cod echipament	:	RO_016061	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.03.2003	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	01.03.2003	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	01.03.2003	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 3

Sistem de detectie scurgeri	:	Rezervor 1 bicompartimentat	☐ Corect
Cod echipament	:	RO_016064	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	01.03.2003	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 3

Sistem de detectie scurgeri	:	Rezervor 2 bicompartimentat	☐ Corect
Cod echipament	:	RO_016065	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	01.03.2003	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 3

Sistem de detectie scurgeri	:	Rezervor 3 bicompartimentat	☐ Corect
Cod echipament	:	RO_016066	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	01.03.2003	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____