

FISA VALIDARE INVENTAR

R1511 - 4 Otelu Rosu



DATE GENERALE STATIE

Cod statie	:	R1511	Data verificarii	:	
Nume statie	:	4 Otelu Rosu	Persoana care verifica	:	
Numar distribuitoare	:	3			
Numar echipamente Sistem masura rezervoare	:			11	
Numar echipamente Rezervoare / sisteme asociate	:			36	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 3 - Pompa 5/6

Cod echipament	:	RO_239417	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	943303/2022	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root	☐ Corect	
Tip echipament	:	HS 1-2	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	24.11.2022	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	130 l/min	☐ Corect	Observatii:
Numar pistoale	:	2	☐ Corect	
Calculator pompa	:	Tatsuno	☐ Corect	

DISTRIBUITOR 2 DIN 3 - Pompa 1/2

Cod echipament	:	RO_239418	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	943301/2022	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	24.11.2022	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	Tatsuno	☐ Corect	

DISTRIBUITOR 3 DIN 3 - Pompa 3/4

Cod echipament	:	RO_239419	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	943302/2022	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	24.11.2022	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	Tatsuno	☐ Corect	

FISA VALIDARE INVENTAR

R1511 - 4 Otelu Rosu



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_004573	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 450	☐ Corect	
Tip echipament	:	Veeder-Root 450 Plus		
		Veeder-Root 450	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 8

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_004574	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/1	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 8

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_004575	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/2	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 8

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_004576	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 8

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_004577	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/2	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1511 - 4 Otelu Rosu



SONDA NIVEL 5 DIN 8

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_004578	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3/1	☐ Corect
Data fabricatiei	:	16.08.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 6 DIN 8

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_004579	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3/2	☐ Corect
Data fabricatiei	:	16.08.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 7 DIN 8

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_004580	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R4/1	☐ Corect
Data fabricatiei	:	16.08.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 8 DIN 8

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_004581	☐ Corect
Serie echipament	:	nefolosit	☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R4/2	☐ Corect
Data fabricatiei	:	16.08.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_004582	☐ Corect
Serie echipament	:	371	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	28.04.1988	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR
R1511 - 4 Otelu Rosu



RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_004583	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	484	☐ Corect	_____
Producator	:	Mecaf_	☐ Corect	_____
Tip echipament	:	Rigla metalica 5m	☐ Corect	_____
Data fabricatiei	:	31.10.2002	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1511 - 4 Otelu Rosu



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 8

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_004584	☐ Corect	
Serie echipament	:	cc165/2011	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	31.10.2002	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	31.10.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	31.10.2002	☐ Corect	

REZERVOR 2 DIN 8

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_004587	☐ Corect	
Serie echipament	:	cc165/2011	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	31.10.2002	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	31.10.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	31.10.2002	☐ Corect	

REZERVOR 3 DIN 8

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Extra 99	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_004590	☐ Corect	
Serie echipament	:	cc171/2011	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	31.10.2002	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	31.10.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	31.10.2002	☐ Corect	

REZERVOR 4 DIN 8

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_004593	☐ Corect	
Serie echipament	:	cc171/2011	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	31.10.2002	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	31.10.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	31.10.2002	☐ Corect	

REZERVOR 5 DIN 8

Rezervor	:	R3/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3/1 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_004596	☐ Corect	

FISA VALIDARE INVENTAR

R1511 - 4 Otelu Rosu



Serie echipament	:	cc166/2011	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	31.10.2002	☐ Corect
Capac Rezervor	:	unknown	☐ Corect
Data fabricatiei	:	31.10.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	31.10.2002	☐ Corect

Observatii:

REZERVOR 6 DIN 8

Rezervor	:	R3/2 bicompartimentat	☐ Corect
Produs	:	R3/2 Diesel Std	☐ Corect
Cod echipament	:	RO_004599	☐ Corect
Serie echipament	:	cc166/2011	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	31.10.2002	☐ Corect
Capac Rezervor	:	unknown	☐ Corect
Data fabricatiei	:	31.10.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	31.10.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

REZERVOR 7 DIN 8

Rezervor	:	R4/1 bicompartimentat	☐ Corect
Produs	:	R4/1 Diesel Std	☐ Corect
Cod echipament	:	RO_004602	☐ Corect
Serie echipament	:	cc164/2011	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	31.10.2002	☐ Corect
Capac Rezervor	:	unknown	☐ Corect
Data fabricatiei	:	31.10.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	31.10.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

REZERVOR 8 DIN 8

Rezervor	:	R4/2 bicompartimentat	☐ Corect
Produs	:	R4/2 Diesel Std	☐ Corect
Cod echipament	:	RO_004605	☐ Corect
Serie echipament	:	nefolosit	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	31.10.2002	☐ Corect
Capac Rezervor	:	unknown	☐ Corect
Data fabricatiei	:	31.10.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	31.10.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 4

Sistem de detectie scurgeri	:	Rezervor 1 bicompartimentat	☐ Corect
Cod echipament	:	RO_004608	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	31.10.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 4

FISA VALIDARE INVENTAR

R1511 - 4 Otelu Rosu



Sistem de detectie scurgeri : Rezervor 2 bicompartimentat ☐ Corect
Cod echipament : RO_004609 ☐ Corect
Serie echipament : ☐ Corect
Producator : SGB ☐ Corect
Data fabricatiei : 31.10.2002 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari
Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 4

Sistem de detectie scurgeri : Rezervor 3 bicompartimentat ☐ Corect
Cod echipament : RO_004610 ☐ Corect
Serie echipament : ☐ Corect
Producator : SGB ☐ Corect
Data fabricatiei : 31.10.2002 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari
Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 4 DIN 4

Sistem de detectie scurgeri : Rezervor 4 bicompartimentat ☐ Corect
Cod echipament : RO_004611 ☐ Corect
Serie echipament : ☐ Corect
Producator : SGB ☐ Corect
Data fabricatiei : 31.10.2002 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari
Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____