

FISA VALIDARE INVENTAR

R1529 - 2 Lugoj



DATE GENERALE STATIE

Cod statie	:	R1529	Data verificarii	:	
Nume statie	:	2 Lugoj	Persoana care verifica	:	
Numar distribuitoare	:	2			
Numar echipamente Sistem masura rezervoare	:			6	
Numar echipamente Rezervoare / sisteme asociate	:			12	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 2 - Pompa 1

Cod echipament	:	RO_009364	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	1-126790-003/06	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	DRESSER WAYNE	☐ Corect	
Tip echipament	:	Monoprodus VR 1	☐ Corect	
Numar dispenser	:	Pompa 1	☐ Corect	
Data fabricatiei	:	10.04.2009	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	130 l/min	☐ Corect	Observatii:
Numar pistoale	:	1	☐ Corect	
Calculator pompa	:	TQC	☐ Corect	

DISTRIBUITOR 2 DIN 2 - Pompa 2

Cod echipament	:	RO_009365	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	1-126792-003/06	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	DRESSER WAYNE	☐ Corect	
Tip echipament	:	Monoprodus	☐ Corect	
Numar dispenser	:	Pompa 2	☐ Corect	
Data fabricatiei	:	10.04.2009	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	130 l/min	☐ Corect	Observatii:
Numar pistoale	:	2	☐ Corect	
Calculator pompa	:	WWC	☐ Corect	

FISA VALIDARE INVENTAR

R1529 - 2 Lugoj



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009367	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	K11209644205008	☐ Corect	
Producator	:	Veeder-Root TLS450	☐ Corect	
Tip echipament	:	Veeder-Root TLS450	☐ Corect	
Data fabricatiei	:	07.06.2011	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009368	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1	☐ Corect	
Data fabricatiei	:	07.06.2011	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009369	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2	☐ Corect	
Data fabricatiei	:	07.06.2011	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009370	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R3	☐ Corect	
Data fabricatiei	:	07.06.2011	☐ Corect	Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009371	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Mecaf_	☐ Corect	
Tip echipament	:	Vas etalon	☐ Corect	
Data fabricatiei	:	24.10.2007	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1529 - 2 Lugoj



RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_009372	☐ Corect
Serie echipament	:	870	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	24.10.2007	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1529 - 2 Lugoj



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 3

Rezervor	:	R1 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009373	☐ Corect	_____
Serie echipament	:		☐ Corect	_____
Producator	:	unknown	☐ Corect	_____
Data fabricatiei	:	12.01.1995	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	_____
Data fabricatiei	:	12.01.1995	☐ Corect	_____
Sistem siguranta preaplin	:	DA	☐ Corect	_____
Data fabricatiei	:	12.01.1995	☐ Corect	_____

REZERVOR 2 DIN 3

Rezervor	:	R2 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2 Diesel Standard	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009376	☐ Corect	_____
Serie echipament	:		☐ Corect	_____
Producator	:	unknown	☐ Corect	_____
Data fabricatiei	:	12.01.1995	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	_____
Data fabricatiei	:	12.01.1995	☐ Corect	_____
Sistem siguranta preaplin	:	DA	☐ Corect	_____
Data fabricatiei	:	12.01.1995	☐ Corect	_____

REZERVOR 3 DIN 3

Rezervor	:	R3 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3 Diesel Standard	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009379	☐ Corect	_____
Serie echipament	:		☐ Corect	_____
Producator	:	unknown	☐ Corect	_____
Data fabricatiei	:	12.01.1995	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	_____
Data fabricatiei	:	12.01.1995	☐ Corect	_____
Sistem siguranta preaplin	:	DA	☐ Corect	_____
Data fabricatiei	:	12.01.1995	☐ Corect	_____

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____