

FISA VALIDARE INVENTAR

R1530 - 3 Lugoj



DATE GENERALE STATIE

Cod statie	: R1530	Data verificarii	:
Nume statie	: 3 Lugoj	Persoana care verifica	:
Numar distribuitoare	: 4		
Numar echipamente Sistem masura rezervoare	:	9	
Numar echipamente Rezervoare / sisteme asociate	:	28	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 4 - Pompa 7/8

Cod echipament	: RO_238923	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 943235	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root SK700-2	☐ Corect	
Tip echipament	: HS 1-2	☐ Corect	
Numar dispenser	: Pompa 7/8	☐ Corect	
Data fabricatiei	: 24.11.2022	☐ Corect	
Numar produse	: 1	☐ Corect	
Debit	: 130 l/min	☐ Corect	Observatii:
Numar pistoale	: 2	☐ Corect	
Calculator pompa	: Tatsuno	☐ Corect	

DISTRIBUITOR 2 DIN 4 - Pompa 1/2

Cod echipament	: RO_238924	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 943232	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root SK700-2	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 1/2	☐ Corect	
Data fabricatiei	: 24.11.2022	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: WWC	☐ Corect	

DISTRIBUITOR 3 DIN 4 - Pompa 3/4

Cod echipament	: RO_238925	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 943233	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root SK700-2	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 3/4	☐ Corect	
Data fabricatiei	: 24.11.2022	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: WWC	☐ Corect	

DISTRIBUITOR 4 DIN 4 - Pompa 5/6

Cod echipament	: RO_238926	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 943234	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root SK700-2	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 5/6	☐ Corect	
Data fabricatiei	: 24.11.2022	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1530 - 3 Lugoj



Numar pistoale	:	8	☐ Corect	_____
Calculator pompa	:	WWC	☐ Corect	_____

FISA VALIDARE INVENTAR

R1530 - 3 Lugoj



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009439	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 350R_	☐ Corect	
Tip echipament	:	Veeder-Root 350R	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009440	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/1 Senzori R1/2	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009441	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/2 Senzori R2/1	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009442	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1 Senzori R2/2	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009443	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/2 Senzori R3/1	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1530 - 3 Lugoj



SONDA NIVEL 5 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_009444	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root	☐ Corect
Tip echipament	:	Sonda R3/1 Senzori R3/2	☐ Corect
Data fabricatiei	:	16.08.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 6 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_009445	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root	☐ Corect
Tip echipament	:	Sonda R3/2 Senzori R5	☐ Corect
Data fabricatiei	:	16.08.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_009446	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Mecaf	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	09.01.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_009447	☐ Corect
Serie echipament	:	479	☐ Corect
Producator	:	Mecaf	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	09.01.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1530 - 3 Lugoj



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 6

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009448	☐ Corect	
Serie echipament	:	74	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	09.01.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	09.01.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	09.01.2002	☐ Corect	

REZERVOR 2 DIN 6

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009451	☐ Corect	
Serie echipament	:	74	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	09.01.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	09.01.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	09.01.2002	☐ Corect	

REZERVOR 3 DIN 6

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Extra 99	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009454	☐ Corect	
Serie echipament	:	78	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	09.01.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	09.01.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	09.01.2002	☐ Corect	

REZERVOR 4 DIN 6

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009457	☐ Corect	
Serie echipament	:	78	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	09.01.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	09.01.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	09.01.2002	☐ Corect	

REZERVOR 5 DIN 6

Rezervor	:	R3/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3/1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009460	☐ Corect	

FISA VALIDARE INVENTAR

R1530 - 3 Lugoj



Serie echipament	:	79	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	09.01.2002	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	09.01.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	09.01.2002	☐ Corect

Observatii:

REZERVOR 6 DIN 6

Rezervor	:	R3/2 bicompartimentat	☐ Corect
Produs	:	R3/2 Diesel Extra	☐ Corect
Cod echipament	:	RO_009463	☐ Corect
Serie echipament	:	79	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	09.01.2002	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	09.01.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	09.01.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 3

Sistem de detectie scurgeri	:	Rezervor 1 bicompartimentat	☐ Corect
Cod echipament	:	RO_009467	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	09.01.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 3

Sistem de detectie scurgeri	:	Rezervor 2 bicompartimentat	☐ Corect
Cod echipament	:	RO_009468	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	09.01.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 3

Sistem de detectie scurgeri	:	Rezervor 3 bicompartimentat	☐ Corect
Cod echipament	:	RO_009469	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	09.01.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____