

FISA VALIDARE INVENTAR

R1532 - 2 Sannicolau Mare



DATE GENERALE STATIE

Cod statie	: R1532	Data verificarii	:
Nume statie	: 2 Sannicolau Mare	Persoana care verifica	:
Numar distribuitoare	: 4		
Numar echipamente Sistem masura rezervoare	:	10	
Numar echipamente Rezervoare / sisteme asociate	:	30	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 4 - Pompa 7/8

Cod echipament	: RO_025249	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 701120	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: GILBARCO VEEDER ROOT	☐ Corect	
Tip echipament	: HS 1-2	☐ Corect	
Numar dispenser	: Pompa 7/8	☐ Corect	
Data fabricatiei	: 01.01.2020	☐ Corect	
Numar produse	: 1	☐ Corect	
Debit	: 130 l/min	☐ Corect	Observatii:
Numar pistoale	: 2	☐ Corect	
Calculator pompa	: Gilbarco	☐ Corect	

DISTRIBUITOR 2 DIN 4 - Pompa 5/6

Cod echipament	: RO_025250	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 701090	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: GILBARCO VEEDER ROOT	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 5/6	☐ Corect	
Data fabricatiei	: 01.01.2020	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: Gilbarco	☐ Corect	

DISTRIBUITOR 3 DIN 4 - Pompa 3/4

Cod echipament	: RO_025251	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 701078	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: GILBARCO VEEDER ROOT	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 3/4	☐ Corect	
Data fabricatiei	: 01.01.2020	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: Gilbarco	☐ Corect	

DISTRIBUITOR 4 DIN 4 - Pompa 1/2

Cod echipament	: RO_025252	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 701083	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: GILBARCO VEEDER ROOT	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 1/2	☐ Corect	
Data fabricatiei	: 01.01.2020	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1532 - 2 Sannicolau Mare



Numar pistoale	:	8	☐ Corect	_____
Calculator pompa	:	Gilbarco	☐ Corect	_____

FISA VALIDARE INVENTAR

R1532 - 2 Sannicolau Mare



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009620	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	S01249853111002	☐ Corect	_____
Producator	:	Veeder-Root 350R_	☐ Corect	_____
Tip echipament	:	Veeder-Root 350R_	☐ Corect	_____
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 7

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009621	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R1/1	☐ Corect	_____
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 7

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009622	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R1/2	☐ Corect	_____
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 7

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009623	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R2/1	☐ Corect	_____
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 7

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009624	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R2/2	☐ Corect	_____
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1532 - 2 Sannicolau Mare



SONDA NIVEL 5 DIN 7

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_009625	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3/1	☐ Corect
Data fabricatiei	:	16.08.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 6 DIN 7

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_009626	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3/2	☐ Corect
Data fabricatiei	:	16.08.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 7 DIN 7

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_009627	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R4	☐ Corect
Data fabricatiei	:	16.08.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_009628	☐ Corect
Serie echipament	:	RO2275-11027	☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	04.01.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_009629	☐ Corect
Serie echipament	:	711	☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	04.01.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1532 - 2 Sannicolau Mare



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 7

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009630	☐ Corect	
Serie echipament	:	50	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	04.01.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	04.01.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	04.01.2002	☐ Corect	

REZERVOR 2 DIN 7

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009633	☐ Corect	
Serie echipament	:	50	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	04.01.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	04.01.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	04.01.2002	☐ Corect	

REZERVOR 3 DIN 7

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009636	☐ Corect	
Serie echipament	:	49	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	04.01.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	04.01.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	04.01.2002	☐ Corect	

REZERVOR 4 DIN 7

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009639	☐ Corect	
Serie echipament	:	49	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	04.01.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	04.01.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	04.01.2002	☐ Corect	

REZERVOR 5 DIN 7

Rezervor	:	R3/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3/1 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009642	☐ Corect	

FISA VALIDARE INVENTAR

R1532 - 2 Sannicolau Mare



Serie echipament	:	51	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	04.01.2002	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	04.01.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	04.01.2002	☐ Corect

Observatii:

REZERVOR 6 DIN 7

Rezervor	:	R3/2 bicompartimentat	☐ Corect
Produs	:	R3/2 Extra 99	☐ Corect
Cod echipament	:	RO_009645	☐ Corect
Serie echipament	:	51	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	04.01.2002	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	04.01.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	04.01.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

REZERVOR 7 DIN 7

Rezervor	:	R4 monocompartimentat	☐ Corect
Produs	:	R4 inactiv	☐ Corect
Cod echipament	:	RO_009648	☐ Corect
Serie echipament	:	FS	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	04.01.2002	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	04.01.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 3

Sistem de detectie scurgeri	:	Rezervor 1 bicompartimentat	☐ Corect
Cod echipament	:	RO_009651	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	04.01.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 3

Sistem de detectie scurgeri	:	Rezervor 2 bicompartimentat	☐ Corect
Cod echipament	:	RO_009652	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	04.01.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 3

Sistem de detectie scurgeri	:	Rezervor 3 bicompartimentat	☐ Corect
Cod echipament	:	RO_009653	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	04.01.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1532 - 2 Sannicolau Mare



VERIFICARE FINALA

Nume: _____

Funcție: _____

Data: _____

Semnatura: _____