

FISA VALIDARE INVENTAR

R1536 - 13 Timisoara



DATE GENERALE STATIE

Cod statie	: R1536	Data verificarii	:
Nume statie	: 13 Timisoara	Persoana care verifica	:
Numar distribuitoare	: 3		
Numar echipamente Sistem masura rezervoare	:	8	
Numar echipamente Rezervoare / sisteme asociate	:	22	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 3 - Pompa 5/6

Cod echipament	: RO_240769	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 973902/2025	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 5/6	☐ Corect	
Data fabricatiei	: 25.07.2025	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: DPX	☐ Corect	

DISTRIBUITOR 2 DIN 3 - Pompa 3/4

Cod echipament	: RO_240770	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 973903/2025	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 3/4	☐ Corect	
Data fabricatiei	: 25.07.2025	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: DPX	☐ Corect	

DISTRIBUITOR 3 DIN 3 - Pompa 1/2

Cod echipament	: RO_240771	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 973904/2025	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4 (DM)	☐ Corect	
Numar dispenser	: Pompa 1/2	☐ Corect	
Data fabricatiei	: 25.07.2025	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	:	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: DPX	☐ Corect	

FISA VALIDARE INVENTAR

R1536 - 13 Timisoara



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_010902	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	TO5258578311001	☐ Corect	
Producator	:	Veeder-Root 450R_	☐ Corect	
Tip echipament	:	Veeder-Root 450 Plus		
		Veeder-Root 450	☐ Corect	
Data fabricatiei	:	20.08.2018	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_010903	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/1 Senzori R1	☐ Corect	
Data fabricatiei	:	20.08.2018	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_010904	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/2 Senzori R2	☐ Corect	
Data fabricatiei	:	20.08.2018	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_010905	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1 Senzori R3/1	☐ Corect	
Data fabricatiei	:	20.08.2018	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_010906	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/2 Senzori R3/2	☐ Corect	
Data fabricatiei	:	20.08.2018	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1536 - 13 Timisoara



SONDA NIVEL 5 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_010907	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Veeder-Root	☐ Corect
Tip echipament	:	Sonda R2/3 Senzori R4	☐ Corect
Data fabricatiei	:	20.08.2018	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_010908	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Mecaf	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	12.04.2006	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_010909	☐ Corect
Serie echipament	:	324	☐ Corect
Prodicator	:	Mecaf	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	11.11.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1536 - 13 Timisoara



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 5

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 OMV Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_010910	☐ Corect	
Serie echipament	:	387/2005	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	12.04.2006	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	12.04.2006	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	12.04.2006	☐ Corect	

REZERVOR 2 DIN 5

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_010913	☐ Corect	
Serie echipament	:	387/2005	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	12.04.2006	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	12.04.2006	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	12.04.2006	☐ Corect	

REZERVOR 3 DIN 5

Rezervor	:	R2/1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_010916	☐ Corect	
Serie echipament	:	391/2005	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	12.04.2006	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	12.04.2006	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	12.04.2006	☐ Corect	

REZERVOR 4 DIN 5

Rezervor	:	R2/2 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 MM95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_010919	☐ Corect	
Serie echipament	:	391/2005	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	12.04.2006	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	12.04.2006	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	12.04.2006	☐ Corect	

REZERVOR 5 DIN 5

Rezervor	:	R2/3 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/3 MM100+	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_010922	☐ Corect	

FISA VALIDARE INVENTAR

R1536 - 13 Timisoara



Serie echipament	:	391/2005	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	12.04.2006	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	12.04.2006	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	12.04.2006	☐ Corect

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 2

Sistem de detectie scurgeri	:	Rezervor 1 bicompartimentat	☐ Corect
Cod echipament	:	RO_010925	☐ Corect
Serie echipament	:	DL4000	☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	12.04.2006	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 2

Sistem de detectie scurgeri	:	Rezervor 2 tricompartimentat	☐ Corect
Cod echipament	:	RO_010926	☐ Corect
Serie echipament	:	DL4000	☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	12.04.2006	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____