

FISA VALIDARE INVENTAR

R1538 - Cornesti



DATE GENERALE STATIE

Cod statie	:	R1538	Data verificarii	:	
Nume statie	:	Cornesti	Persoana care verifica	:	
Numar distribuitoare	:	4			
Numar echipamente Sistem masura rezervoare	:			9	
Numar echipamente Rezervoare / sisteme asociate	:			27	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 4 - Pompa 7/8

Cod echipament	:	RO_009822	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	98/56674	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantium 500T	☐ Corect	
Tip echipament	:	HS 1-2	☐ Corect	
Numar dispenser	:	Pompa 7/8	☐ Corect	
Data fabricatiei	:	06.01.1999	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	130 l/min	☐ Corect	Observatii:
Numar pistoale	:	2	☐ Corect	
Calculator pompa	:	WWC	☐ Corect	

DISTRIBUITOR 2 DIN 4 - Pompa 3/4

Cod echipament	:	RO_009823	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D0103042	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantium 500T	☐ Corect	
Tip echipament	:	MPD 4/8 VR 3/6	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	WWC	☐ Corect	

DISTRIBUITOR 3 DIN 4 - Pompa 5/6

Cod echipament	:	RO_009824	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D0103045	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantium 500T	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	WWC	☐ Corect	

DISTRIBUITOR 4 DIN 4 - Pompa 1/2

Cod echipament	:	RO_009825	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D0103047	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantium 500T	☐ Corect	
Tip echipament	:	MPD 4/8 VR 3/6	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	
Numar produse	:	3	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1538 - Cornesti



Numar pistoale	:	8	☐ Corect	_____
Calculator pompa	:	WWC	☐ Corect	_____

FISA VALIDARE INVENTAR

R1538 - Cornesti



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009827	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 350R_	☐ Corect	
Tip echipament	:	Veeder-Root 350R	☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009828	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/1	☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009829	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/2	☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009830	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1	☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_009831	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/2	☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1538 - Cornesti



SONDA NIVEL 5 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_009832	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3/1	☐ Corect
Data fabricatiei	:	06.01.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 6 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_009833	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3/2	☐ Corect
Data fabricatiei	:	06.01.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_009835	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	13.03.2024	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_009836	☐ Corect
Serie echipament	:	515	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	06.01.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1538 - Cornesti



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 6

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009837	☐ Corect	
Serie echipament	:	88	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	

REZERVOR 2 DIN 6

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009840	☐ Corect	
Serie echipament	:	88	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	

REZERVOR 3 DIN 6

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009843	☐ Corect	
Serie echipament	:	89	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	

REZERVOR 4 DIN 6

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009846	☐ Corect	
Serie echipament	:	89	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	06.01.2001	☐ Corect	

REZERVOR 5 DIN 6

Rezervor	:	R3/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3/1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_009849	☐ Corect	

FISA VALIDARE INVENTAR

R1538 - Cornesti



Serie echipament	:	90	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	06.01.2001	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	06.01.2001	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	06.01.2001	☐ Corect

Observatii:

REZERVOR 6 DIN 6

Rezervor	:	R3/2 bicompartimentat	☐ Corect
Produs	:	R3/2 Standard 95	☐ Corect
Cod echipament	:	RO_009852	☐ Corect
Serie echipament	:	90	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	06.01.2001	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	06.01.2001	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	06.01.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 3

Sistem de detectie scurgeri	:	Rezervor 1 bicompartimentat	☐ Corect
Cod echipament	:	RO_009858	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	06.01.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 3

Sistem de detectie scurgeri	:	Rezervor 2 bicompartimentat	☐ Corect
Cod echipament	:	RO_009859	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	06.01.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 3

Sistem de detectie scurgeri	:	Rezervor 3 bicompartimentat	☐ Corect
Cod echipament	:	RO_009860	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	06.01.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Funcție: _____
Data: _____
Semnatura: _____