

FISA VALIDARE INVENTAR

R1548 - 5 Gradiste



DATE GENERALE STATIE

Cod statie	:	R1548	Data verificarii	:	
Nume statie	:	5 Gradiste	Persoana care verifica	:	
Numar distribuitoare	:	1			
Numar echipamente Sistem masura rezervoare	:			6	
Numar echipamente Rezervoare / sisteme asociate	:			13	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 1 - Pompa 1/2

Cod echipament	:	RO_226458	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D0745302	☐ Corect	Valori corectate / informatii de pe placuta:
Prodicator	:	Tokheim_Quantium 500T	☐ Corect	
Tip echipament	:	MPD 3/6 VR 1/2	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2007	☐ Corect	
Numar produse	:	3	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	6	☐ Corect	
Calculator pompa	:	WWC	☐ Corect	

FISA VALIDARE INVENTAR

R1548 - 5 Gradiste



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_226460	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	ELECTRONIC_	☐ Corect	
Tip echipament	:	ELECTRONIC OPTILEVEL		
		Optilevel C104M	☐ Corect	
Data fabricatiei	:	31.12.2007	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_226461	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/1	☐ Corect	
Data fabricatiei	:	31.12.2007	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_226462	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/2	☐ Corect	
Data fabricatiei	:	31.12.2007	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_226463	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/3	☐ Corect	
Data fabricatiei	:	31.12.2007	☐ Corect	Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_226464	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	40	☐ Corect	
Producator	:	DELTA IMPEX	☐ Corect	
Tip echipament	:	Vas etalon	☐ Corect	
Data fabricatiei	:	01.01.2008	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1548 - 5 Gradiste



RIGLA GRADATA 1 DIN 1

Echipament : Rigla Gradata
Cod echipament : RO_226465
Serie echipament : 281
Producator : Mecaf_
Tip echipament : Rigla metalica 4m
Data fabricatiei : 04.09.2019

☐ Corect
☐ Corect
☐ Corect
☐ Corect
☐ Corect
☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1548 - 5 Gradiste



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 3

Rezervor	:	R1/1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_226466	☐ Corect	_____
Serie echipament	:	648	☐ Corect	_____
Producator	:	unknown	☐ Corect	_____
Data fabricatiei	:	01.01.2007	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	_____
Data fabricatiei	:	31.12.2007	☐ Corect	_____
Sistem siguranta preaplin	:	DA	☐ Corect	_____
Data fabricatiei	:	31.12.2007	☐ Corect	_____

REZERVOR 2 DIN 3

Rezervor	:	R1/2 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_226469	☐ Corect	_____
Serie echipament	:	648	☐ Corect	_____
Producator	:	unknown	☐ Corect	_____
Data fabricatiei	:	01.01.2007	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	_____
Data fabricatiei	:	31.12.2007	☐ Corect	_____
Sistem siguranta preaplin	:	DA	☐ Corect	_____
Data fabricatiei	:	31.12.2007	☐ Corect	_____

REZERVOR 3 DIN 3

Rezervor	:	R1/3 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/3 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_226472	☐ Corect	_____
Serie echipament	:	648	☐ Corect	_____
Producator	:	unknown	☐ Corect	_____
Data fabricatiei	:	01.01.2007	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	_____
Data fabricatiei	:	31.12.2007	☐ Corect	_____
Sistem siguranta preaplin	:	DA	☐ Corect	_____
Data fabricatiei	:	31.12.2007	☐ Corect	_____

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 1

Sistem de detectie scurgeri	:	Rezervor 1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_226475	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	3311	☐ Corect	_____
Producator	:	AFRISO	☐ Corect	_____
Data fabricatiei	:	01.01.2007	☐ Corect	Observatii:

VERIFICARE FINALA

Nume: _____
Funcție: _____

FISA VALIDARE INVENTAR

R1548 - 5 Gradiste



Data: _____
Semnatura: _____