

FISA VALIDARE INVENTAR

R1552 - 9 Cocorilor



DATE GENERALE STATIE

Cod statie	:	R1552	Data verificarii	:	
Nume statie	:	9 Cocorilor	Persoana care verifica	:	
Numar distribuitoare	:	3			
Numar echipamente Sistem masura rezervoare	:			7	
Numar echipamente Rezervoare / sisteme asociate	:			18	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 3 - Pompa 1/2

Cod echipament	:	RO_227408	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	684612	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	GILBARCO	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	APOLLO	☐ Corect	

DISTRIBUITOR 2 DIN 3 - Pompa 3/4

Cod echipament	:	RO_227409	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	684610	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	GILBARCO	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	APOLLO	☐ Corect	

DISTRIBUITOR 3 DIN 3 - Pompa 5/6

Cod echipament	:	RO_227410	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	684611	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	GILBARCO	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	APOLLO	☐ Corect	

FISA VALIDARE INVENTAR

R1552 - 9 Cocorilor



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_227412	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root 450R	☐ Corect	_____
Tip echipament	:	Veeder-Root 450R	☐ Corect	_____
Data fabricatiei	:	16.01.2020	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_227413	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R1/1	☐ Corect	_____
Data fabricatiei	:	16.01.2020	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_227414	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R1/2	☐ Corect	_____
Data fabricatiei	:	16.01.2020	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_227415	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R2/1	☐ Corect	_____
Data fabricatiei	:	16.01.2020	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_227416	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R2/2	☐ Corect	_____
Data fabricatiei	:	16.01.2020	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1552 - 9 Cocorilor



VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_227417	☐ Corect
Serie echipament	:	430	☐ Corect
Producator	:	DELTA IMPEX	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	01.01.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_227418	☐ Corect
Serie echipament	:	321	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica 5m	☐ Corect
Data fabricatiei	:	11.11.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1552 - 9 Cocorilor



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 4

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_227419	☐ Corect	
Serie echipament	:	19147	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	16.01.2020	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	16.01.2020	☐ Corect	

REZERVOR 2 DIN 4

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_227422	☐ Corect	
Serie echipament	:	19147	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	16.01.2020	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	16.01.2020	☐ Corect	

REZERVOR 3 DIN 4

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_227425	☐ Corect	
Serie echipament	:	19148	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	16.01.2020	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	16.01.2020	☐ Corect	

REZERVOR 4 DIN 4

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Extra 99	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_227428	☐ Corect	
Serie echipament	:	19148	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2019	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	16.01.2020	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	16.01.2020	☐ Corect	

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 2

FISA VALIDARE INVENTAR

R1552 - 9 Cocorilor



Sistem de detectie scurgeri : Rezervor 1 bicompartimentat ☐ Corect
Cod echipament : RO_227431 ☐ Corect
Serie echipament : FS ☐ Corect
Producator : LECKANZEIGER ☐ Corect
Data fabricatiei : 16.01.2020 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 2

Sistem de detectie scurgeri : Rezervor 2 bicompartimentat ☐ Corect
Cod echipament : RO_227432 ☐ Corect
Serie echipament : FS ☐ Corect
Producator : LECKANZEIGER ☐ Corect
Data fabricatiei : 16.01.2020 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____

Funcție: _____

Data: _____

Semnatura: _____