

FISA VALIDARE INVENTAR

R1559 - 18 Nadlac



DATE GENERALE STATIE

Cod statie	: R1559	Data verificarii	:
Nume statie	: 18 Nadlac	Persoana care verifica	:
Numar distribuitoare	: 4		
Numar echipamente Sistem masura rezervoare	:	9	
Numar echipamente Rezervoare / sisteme asociate	:	23	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 4 - Pompa 7/8

Cod echipament	: RO_227745	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 684840	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root_SK700-2/ADBLUE		☐ Corect
Tip echipament	: MPD 1/2 (Ad Blue - OMV)	☐ Corect	
Numar dispenser	: Pompa 7/8	☐ Corect	
Data fabricatiei	: 01.01.2018	☐ Corect	
Numar produse	: 1	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 2	☐ Corect	
Calculator pompa	:	☐ Corect	

DISTRIBUITOR 2 DIN 4 - Pompa 1/2

Cod echipament	: RO_240705	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 972750/2025	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 1/2	☐ Corect	
Data fabricatiei	: 25.06.2025	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	:	☐ Corect	

DISTRIBUITOR 3 DIN 4 - Pompa 3/4

Cod echipament	: RO_240706	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 972751/2025	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 3/4	☐ Corect	
Data fabricatiei	: 25.06.2025	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	:	☐ Corect	

DISTRIBUITOR 4 DIN 4 - Pompa 5/6

Cod echipament	: RO_240707	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 972752/2025	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 5/6	☐ Corect	
Data fabricatiei	: 25.06.2025	☐ Corect	
Numar produse	: 4	☐ Corect	

FISA VALIDARE INVENTAR

R1559 - 18 Nadlac



Debit : 40 l/min
Numar pistoale : 8
Calculator pompa :

[] Corect
[] Corect
[] Corect

Observatii:

FISA VALIDARE INVENTAR

R1559 - 18 Nadlac



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_227753	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Mecaf_	☐ Corect	
Tip echipament	:	Vas etalon	☐ Corect	
Data fabricatiei	:	05.10.2007	☐ Corect	Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_227754	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	802	☐ Corect	
Producator	:	Mecaf_	☐ Corect	
Tip echipament	:	Rigla metalica 5m	☐ Corect	
Data fabricatiei	:	25.02.2019	☐ Corect	Observatii:

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_236838	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 450R	☐ Corect	
Tip echipament	:	Veeder-Root 450R	☐ Corect	
Data fabricatiei	:	01.01.2020	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_236840	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/1	☐ Corect	
Data fabricatiei	:	01.09.2020	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_236841	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/2	☐ Corect	
Data fabricatiei	:	01.09.2020	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1559 - 18 Nadlac



SONDA NIVEL 3 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_236842	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2/1	☐ Corect
Data fabricatiei	:	01.09.2020	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 4 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_236843	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2/2	☐ Corect
Data fabricatiei	:	01.09.2020	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 5 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_236844	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2/3	☐ Corect
Data fabricatiei	:	01.09.2020	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 6 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_236845	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R6 AdBlue	☐ Corect
Data fabricatiei	:	10.09.2020	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1559 - 18 Nadlac



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 6

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 OMV Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_227755	☐ Corect	
Serie echipament	:	380A	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2007	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	05.10.2007	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	05.10.2007	☐ Corect	

REZERVOR 2 DIN 6

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_227758	☐ Corect	
Serie echipament	:	380B	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2007	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	05.10.2007	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	05.10.2007	☐ Corect	

REZERVOR 3 DIN 6

Rezervor	:	R2/1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 MM 100+	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_227761	☐ Corect	
Serie echipament	:	793A	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2006	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	05.10.2007	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	05.10.2007	☐ Corect	

REZERVOR 4 DIN 6

Rezervor	:	R2/2 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 MM 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_227764	☐ Corect	
Serie echipament	:	793B	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2006	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	05.10.2007	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	05.10.2007	☐ Corect	

REZERVOR 5 DIN 6

Rezervor	:	R2/3 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/3 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_227767	☐ Corect	

FISA VALIDARE INVENTAR

R1559 - 18 Nadlac



Serie echipament	:	793C	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.01.2006	☐ Corect
Capac Rezervor	:	unknown	☐ Corect
Data fabricatiei	:	05.10.2007	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	05.10.2007	☐ Corect

Observatii:

REZERVOR 6 DIN 6

Rezervor	:	R4 monocompartmentat Adblue/Container	☐ Corect
corecte ☐ Necesita modificari			☐ Datele sunt
Produs	:	R4 Adblue	☐ Corect
Cod echipament	:	RO_227770	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	05.10.2007	☐ Corect
Capac Rezervor	:	Tank shaft incl. Covers (not for AdBlue container)	☐ Corect
Data fabricatiei	:	05.10.2007	☐ Corect

Valori corectate / informatii de pe placuta:

Observatii:

☐ Corect

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____