

FISA VALIDARE INVENTAR

R1576 - 2 Alba Iulia



DATE GENERALE STATIE

Cod statie	:	R1576	Data verificarii	:	
Nume statie	:	2 Alba Iulia	Persoana care verifica	:	
Numar distribuitoare	:	3			
Numar echipamente Sistem masura rezervoare	:			9	
Numar echipamente Rezervoare / sisteme asociate	:			27	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 3 - Pompa 5/6

Cod echipament	:	RO_025253	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	701106	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	GILBARCO VEEDER ROOT	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4 DM	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	01.01.2020	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	70 l/min	☐ Corect	Observatii:
Numar pistoale	:	2	☐ Corect	
Calculator pompa	:	Gilbarco	☐ Corect	

DISTRIBUITOR 2 DIN 3 - Pompa 1/2

Cod echipament	:	RO_025254	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	701096	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	GILBARCO VEEDER ROOT	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2020	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	Gilbarco	☐ Corect	

DISTRIBUITOR 3 DIN 3 - Pompa 3/4

Cod echipament	:	RO_025255	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	701103	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	GILBARCO VEEDER ROOT	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2020	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	Gilbarco	☐ Corect	

FISA VALIDARE INVENTAR

R1576 - 2 Alba Iulia



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013451	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	B0890962817012	☐ Corect	_____
Producator	:	Veeder-Root 350R_	☐ Corect	_____
Tip echipament	:	Veeder-Root 350R	☐ Corect	_____
Data fabricatiei	:	31.12.2001	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013452	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R1/1 Senzori R1	☐ Corect	_____
Data fabricatiei	:	31.12.2001	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013453	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R1/2 Senzori R2	☐ Corect	_____
Data fabricatiei	:	31.12.2001	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013454	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R2/1 Senzori R3/1	☐ Corect	_____
Data fabricatiei	:	31.12.2001	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013455	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R2/2 Senzori R3/2	☐ Corect	_____
Data fabricatiei	:	31.12.2001	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1576 - 2 Alba Iulia



SONDA NIVEL 5 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_013456	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root	☐ Corect
Tip echipament	:	Sonda R3/1 Senzori R4	☐ Corect
Data fabricatiei	:	31.12.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 6 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_013457	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root	☐ Corect
Tip echipament	:	Sonda R3/2 Senzori R5	☐ Corect
Data fabricatiei	:	31.12.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_013458	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Mecaf	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	31.12.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_013459	☐ Corect
Serie echipament	:	910	☐ Corect
Producator	:	Mecaf	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	31.12.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1576 - 2 Alba Iulia



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 6

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013460	☐ Corect	
Serie echipament	:	130/1	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	31.12.2001	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	31.12.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	31.12.2001	☐ Corect	

REZERVOR 2 DIN 6

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013463	☐ Corect	
Serie echipament	:	130/2	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	31.12.2001	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	31.12.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	31.12.2001	☐ Corect	

REZERVOR 3 DIN 6

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013466	☐ Corect	
Serie echipament	:	131/1	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	31.12.2001	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	31.12.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	31.12.2001	☐ Corect	

REZERVOR 4 DIN 6

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013469	☐ Corect	
Serie echipament	:	131/2	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	31.12.2001	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	31.12.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	31.12.2001	☐ Corect	

REZERVOR 5 DIN 6

Rezervor	:	R3/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3/1 Extra 99	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013472	☐ Corect	

FISA VALIDARE INVENTAR

R1576 - 2 Alba Iulia



Serie echipament	:	132/2	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	31.12.2001	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	31.12.2001	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	31.12.2001	☐ Corect

Observatii:

REZERVOR 6 DIN 6

Rezervor	:	R3/2 bicompartimentat	☐ Corect
Produs	:	R3/2 Standard 95	☐ Corect
Cod echipament	:	RO_013475	☐ Corect
Serie echipament	:	132/1	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	31.12.2001	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	31.12.2001	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	31.12.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 3

Sistem de detectie scurgeri	:	Rezervor 1 bicompartimentat	☐ Corect
Cod echipament	:	RO_013478	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	31.12.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 3

Sistem de detectie scurgeri	:	Rezervor 2 bicompartimentat	☐ Corect
Cod echipament	:	RO_013479	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	31.12.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 3

Sistem de detectie scurgeri	:	Rezervor 3 bicompartimentat	☐ Corect
Cod echipament	:	RO_013480	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	31.12.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____