

FISA VALIDARE INVENTAR

R1578 - Blaj



DATE GENERALE STATIE

Cod statie	:	R1578	Data verificarii	:	
Nume statie	:	Blaj	Persoana care verifica	:	
Numar distribuitoare	:	2			
Numar echipamente Sistem masura rezervoare	:			6	
Numar echipamente Rezervoare / sisteme asociate	:			13	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 2 - Pompa 3/4

Cod echipament	:	RO_013623	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	313704	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Desser Wayne Pignone_	☐ Corect	
Tip echipament	:	MPD 3/6 VR 1/2	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2006	☐ Corect	
Numar produse	:	3	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	6	☐ Corect	
Calculator pompa	:	DPX	☐ Corect	

DISTRIBUITOR 2 DIN 2 - Pompa 1/2

Cod echipament	:	RO_240842	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	701109/2020	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	:	MPD 3/6 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	31.07.2020	☐ Corect	
Numar produse	:		☐ Corect	
Debit	:		☐ Corect	Observatii:
Numar pistoale	:		☐ Corect	
Calculator pompa	:		☐ Corect	

FISA VALIDARE INVENTAR

R1578 - Blaj



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013625	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	2700036	☐ Corect	_____
Producator	:	ELECTRONIC _	☐ Corect	_____
Tip echipament	:	ELECTRONIC OPTILEVEL		_____
		Optilevel C104M	☐ Corect	
Data fabricatiei	:	26.04.2007	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013626	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	ELECTRONIC _	☐ Corect	_____
Tip echipament	:	Sonda R1/1	☐ Corect	_____
Data fabricatiei	:	26.04.2007	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013627	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	ELECTRONIC _	☐ Corect	_____
Tip echipament	:	Sonda R1/2	☐ Corect	_____
Data fabricatiei	:	26.04.2007	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013628	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	ELECTRONIC _	☐ Corect	_____
Tip echipament	:	Sonda R1/3	☐ Corect	_____
Data fabricatiei	:	26.04.2007	☐ Corect	Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013629	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	220/2008	☐ Corect	_____
Producator	:	Mecaf_	☐ Corect	_____
Tip echipament	:	Vas etalon	☐ Corect	_____
Data fabricatiei	:	26.04.2007	☐ Corect	Observatii:

FISA VALIDARE INVENTAR
R1578 - Blaj



RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013630	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	952	☐ Corect	_____
Producator	:	Mecaf_	☐ Corect	_____
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect	_____
Data fabricatiei	:	26.04.2007	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1578 - Blaj



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 3

Rezervor	:	R1/1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013631	☐ Corect	_____
Serie echipament	:	507	☐ Corect	_____
Producator	:	unknown	☐ Corect	_____
Data fabricatiei	:	01.01.2007	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	_____
Data fabricatiei	:	26.04.2007	☐ Corect	_____
Sistem siguranta preaplin	:	DA	☐ Corect	_____
Data fabricatiei	:	26.04.2007	☐ Corect	_____

REZERVOR 2 DIN 3

Rezervor	:	R1/2 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013634	☐ Corect	_____
Serie echipament	:	507	☐ Corect	_____
Producator	:	unknown	☐ Corect	_____
Data fabricatiei	:	26.04.2007	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	_____
Data fabricatiei	:	26.04.2007	☐ Corect	_____
Sistem siguranta preaplin	:	DA	☐ Corect	_____
Data fabricatiei	:	26.04.2007	☐ Corect	_____

REZERVOR 3 DIN 3

Rezervor	:	R1/3 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/3 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013637	☐ Corect	_____
Serie echipament	:	507	☐ Corect	_____
Producator	:	unknown	☐ Corect	_____
Data fabricatiei	:	26.04.2007	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	_____
Data fabricatiei	:	26.04.2007	☐ Corect	_____
Sistem siguranta preaplin	:	DA	☐ Corect	_____
Data fabricatiei	:	26.04.2007	☐ Corect	_____

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 1

Sistem de detectie scurgeri	:	Rezervor 1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013640	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	SGB	☐ Corect	_____
Data fabricatiei	:	26.04.2007	☐ Corect	Observatii:

VERIFICARE FINALA

Nume: _____
Funcție: _____

FISA VALIDARE INVENTAR

R1578 - Blaj



Data: _____
Semnatura: _____