

FISA VALIDARE INVENTAR

R1580 - 2 Sebes



DATE GENERALE STATIE

Cod statie	:	R1580	Data verificarii	:	
Nume statie	:	2 Sebes	Persoana care verifica	:	
Numar distribuitoare	:	1			
Numar echipamente Sistem masura rezervoare	:				7
Numar echipamente Rezervoare / sisteme asociate	:				18

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 1 - Pompa 1/2

Cod echipament	:	RO_013719	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D1651035	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantium 510	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2016	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	WWC	☐ Corect	

FISA VALIDARE INVENTAR

R1580 - 2 Sebes



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013721	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	K10208966920012	☐ Corect	_____
Producator	:	Veeder-Root 350R_	☐ Corect	_____
Tip echipament	:	Veeder-Root 350R_	☐ Corect	_____
Data fabricatiei	:	18.07.2011	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013722	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R1/1 Senzori R1	☐ Corect	_____
Data fabricatiei	:	18.07.2011	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013723	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R1/2 Senzori R2	☐ Corect	_____
Data fabricatiei	:	18.07.2011	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013724	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R2/1 Senzori R3/1	☐ Corect	_____
Data fabricatiei	:	18.07.2011	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013725	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R2/2 Senzori R3/2	☐ Corect	_____
Data fabricatiei	:	18.07.2011	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1580 - 2 Sebes



VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_013726	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	25.10.1999	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_013727	☐ Corect
Serie echipament	:	640	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	25.10.1999	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1580 - 2 Sebes



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 4

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013728	☐ Corect	
Serie echipament	:	505/A	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	25.10.1999	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	25.10.1999	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	25.10.1999	☐ Corect	

REZERVOR 2 DIN 4

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013731	☐ Corect	
Serie echipament	:	505/B	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	25.10.1999	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	25.10.1999	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	25.10.1999	☐ Corect	

REZERVOR 3 DIN 4

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013734	☐ Corect	
Serie echipament	:	506/A	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	25.10.1999	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	25.10.1999	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	25.10.1999	☐ Corect	

REZERVOR 4 DIN 4

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013737	☐ Corect	
Serie echipament	:	506/B	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	25.10.1999	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	25.10.1999	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	25.10.1999	☐ Corect	

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 2

FISA VALIDARE INVENTAR

R1580 - 2 Sebes



Sistem de detectie scurgeri : Rezervor 1 bicompartimentat ☐ Corect
Cod echipament : RO_013740 ☐ Corect
Serie echipament : ☐ Corect
Producator : SGB ☐ Corect
Data fabricatiei : 25.10.1999 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 2

Sistem de detectie scurgeri : Rezervor 2 bicompartimentat ☐ Corect
Cod echipament : RO_013741 ☐ Corect
Serie echipament : ☐ Corect
Producator : SGB ☐ Corect
Data fabricatiei : 25.10.1999 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____