

FISA VALIDARE INVENTAR

R1589 - 3 Oradea



DATE GENERALE STATIE

Cod statie	: R1589	Data verificarii	:
Nume statie	: 3 Oradea	Persoana care verifica	:
Numar distribuitoare	: 6		
Numar echipamente Sistem masura rezervoare	:	10	
Numar echipamente Rezervoare / sisteme asociate	:	27	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 6 - Pompa 1/2

Cod echipament	: RO_238353	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 931420	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 1/2	☐ Corect	
Data fabricatiei	: 06.06.2022	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	:	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: Apollo	☐ Corect	

DISTRIBUITOR 2 DIN 6 - Pompa 3/4

Cod echipament	: RO_238354	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 931419	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 3/4	☐ Corect	
Data fabricatiei	: 06.06.2022	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	:	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: Apollo	☐ Corect	

DISTRIBUITOR 3 DIN 6 - Pompa 5/6

Cod echipament	: RO_238355	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 931417	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 5/6	☐ Corect	
Data fabricatiei	: 06.06.2022	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	:	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: Apollo	☐ Corect	

DISTRIBUITOR 4 DIN 6 - Pompa 7/8

Cod echipament	: RO_238356	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 931418	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 7/8	☐ Corect	
Data fabricatiei	: 06.06.2022	☐ Corect	
Numar produse	: 1	☐ Corect	
Debit	: 80 l/min	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1589 - 3 Oradea



Numar pistoale : 2 ☐ Corect
Calculator pompa : Apollo ☐ Corect

DISTRIBUITOR 5 DIN 6 - Pompa 9/10

Cod echipament : RO_238357 ☐ Corect
Serie echipament : 931422 ☐ Corect
Producator : Gilbarco Veeder-Root ☐ Corect
Tip echipament : Pompa Ad Blue ☐ Corect
Numar dispenser : Pompa 9/10 ☐ Corect
Data fabricatiei : 06.06.2022 ☐ Corect
Numar produse : 1 ☐ Corect
Debit : 80 l/min ☐ Corect
Numar pistoale : 2 ☐ Corect
Calculator pompa : Apollo ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DISTRIBUITOR 6 DIN 6 - Pompa 11/12

Cod echipament : RO_238358 ☐ Corect
Serie echipament : 931421 ☐ Corect
Producator : Gilbarco Veeder-Root ☐ Corect
Tip echipament : Pompa Ad Blue ☐ Corect
Numar dispenser : Pompa 11/12 ☐ Corect
Data fabricatiei : 06.06.2022 ☐ Corect
Numar produse : 1 ☐ Corect
Debit : 80 l/min ☐ Corect
Numar pistoale : 2 ☐ Corect
Calculator pompa : Apollo ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1589 - 3 Oradea



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 2

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_238281	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 450R	☐ Corect	
Tip echipament	:	Veeder-Root 450R	☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	Observatii:

CONSOLA ATG 2 DIN 2

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_238282	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Start Italiana	☐ Corect	
Tip echipament	:	MAGLINK-LX PRO GAUGE	☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_238283	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Start Italiana	☐ Corect	
Tip echipament	:	MAGLINK-LX PRO GAUGE		
		Senzori R1/1	☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_238284	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Start Italiana	☐ Corect	
Tip echipament	:	MAGLINK-LX PRO GAUGE		
		Senzori R1/2	☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_238285	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Start Italiana	☐ Corect	
Tip echipament	:	MAGLINK-LX PRO GAUGE		
		Senzori R2/1	☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1589 - 3 Oradea



SONDA NIVEL 4 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_238286	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Start Italiana_	☐ Corect	_____
Tip echipament	:	MAGLINK-LX PRO GAUGE		_____
		Senzori R2/2	☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	Observatii:

SONDA NIVEL 5 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_238287	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Start Italiana_	☐ Corect	_____
Tip echipament	:	MAGLINK-LX PRO GAUGE		_____
		Senzori R3	☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	Observatii:

SONDA NIVEL 6 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_238288	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Start Italiana_	☐ Corect	_____
Tip echipament	:	MAGLINK-LX PRO GAUGE		_____
		Senzori R4	☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_238289	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	21459	☐ Corect	_____
Producator	:	unknown_	☐ Corect	_____
Tip echipament	:	Vas etalon	☐ Corect	_____
Data fabricatiei	:	24.06.2022	☐ Corect	Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_238290	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	928	☐ Corect	_____
Producator	:	Mecaf_	☐ Corect	_____
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect	_____
Data fabricatiei	:	19.12.2020	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1589 - 3 Oradea



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 6

Rezervor	:	R1/1 Extra 99	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Extra 99	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_238316	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown_	☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	

REZERVOR 2 DIN 6

Rezervor	:	R1/2 Standard 95	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_238317	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown_	☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	

REZERVOR 3 DIN 6

Rezervor	:	R2/1 Diesel Extra	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_238318	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown_	☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	

REZERVOR 4 DIN 6

Rezervor	:	R2/2 Motorina Std	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Motorina Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_238319	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown_	☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	24.06.2022	☐ Corect	

REZERVOR 5 DIN 6

Rezervor	:	R3 Motorina Std	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3 Motorina Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_238320	☐ Corect	

FISA VALIDARE INVENTAR

R1589 - 3 Oradea



Serie echipament	:	FS	☐ Corect
Producator	:	unknown_	☐ Corect
Data fabricatiei	:	24.06.2022	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	24.06.2022	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	24.06.2022	☐ Corect

Observatii:

REZERVOR 6 DIN 6

Rezervor	:	R4 AdBlue	☐ Corect
Produs	:	R4 AdBlue	☐ Corect
Cod echipament	:	RO_238321	☐ Corect
Serie echipament	:	FS	☐ Corect
Producator	:	unknown_	☐ Corect
Data fabricatiei	:	24.06.2022	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	24.06.2022	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	24.06.2022	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 3

Sistem de detectie scurgeri	:	Rezervor 1 bicompartimentat	☐ Corect
Cod echipament	:	RO_238300	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB_	☐ Corect
Data fabricatiei	:	24.06.2022	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 3

Sistem de detectie scurgeri	:	Rezervor 2 tricompartimentat	☐ Corect
Cod echipament	:	RO_238301	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB_	☐ Corect
Data fabricatiei	:	24.06.2022	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 3

Sistem de detectie scurgeri	:	Rezervor 3 monocompartimentat	☐ Corect
Cod echipament	:	RO_238302	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB_	☐ Corect
Data fabricatiei	:	24.06.2022	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Funcție: _____
Data: _____
Semnatura: _____