

FISA VALIDARE INVENTAR

R1590 - 4 Oradea



DATE GENERALE STATIE

Cod statie	:	R1590	Data verificarii	:	
Nume statie	:	4 Oradea	Persoana care verifica	:	
Numar distribuitoare	:	1			
Numar echipamente Sistem masura rezervoare	:				6
Numar echipamente Rezervoare / sisteme asociate	:				13

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 1 - Pompa 1/2

Cod echipament	:	RO_206345	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	313716	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	DRESSER WAYNE PIGNONE	☐ Corect	
Tip echipament	:	MPD 3/6 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2006	☐ Corect	
Numar produse	:	3	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	3	☐ Corect	
Calculator pompa	:	DPX-F2	☐ Corect	

FISA VALIDARE INVENTAR

R1590 - 4 Oradea



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_206346	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	270064	☐ Corect	_____
Producator	:	ELECTRONIC	☐ Corect	_____
Tip echipament	:	ELECTRONIC OPTILEVEL	☐ Corect	_____
Data fabricatiei	:	02.10.2007	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_206347	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root	☐ Corect	_____
Tip echipament	:	Sonda R1/1	☐ Corect	_____
Data fabricatiei	:	02.10.2007	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_206348	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root	☐ Corect	_____
Tip echipament	:	Sonda R1/2	☐ Corect	_____
Data fabricatiei	:	02.10.2007	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_206349	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root	☐ Corect	_____
Tip echipament	:	Sonda R1/3	☐ Corect	_____
Data fabricatiei	:	02.10.2007	☐ Corect	Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_206350	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	21	☐ Corect	_____
Producator	:	DELTA IMPEX	☐ Corect	_____
Tip echipament	:	Vas etalon	☐ Corect	_____
Data fabricatiei	:	01.01.2007	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1590 - 4 Oradea



RIGLA GRADATA 1 DIN 1

Echipament : Rigla Gradata
Cod echipament : RO_206351
Serie echipament : 402
Producator : Mecaf_
Tip echipament : Rigla metalica
Data fabricatiei : 08.08.2018

☐ Corect
☐ Corect
☐ Corect
☐ Corect
☐ Corect
☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1590 - 4 Oradea



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 3

Rezervor	:	R1/1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_206352	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	02.10.2007	☐ Corect	Observatii:
Capac Rezervor	:	FIBRALITE FL76	☐ Corect	
Data fabricatiei	:	02.10.2007	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	02.10.2007	☐ Corect	

REZERVOR 2 DIN 3

Rezervor	:	R1/2 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Super 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_206355	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	02.10.2007	☐ Corect	Observatii:
Capac Rezervor	:	FIBRALITE FL76	☐ Corect	
Data fabricatiei	:	02.10.2007	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	02.10.2007	☐ Corect	

REZERVOR 3 DIN 3

Rezervor	:	R1/3 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/3 MM100	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_206358	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	02.10.2007	☐ Corect	Observatii:
Capac Rezervor	:	FIBRALITE FL76	☐ Corect	
Data fabricatiei	:	02.10.2007	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	02.10.2007	☐ Corect	

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 1

Sistem de detectie scurgeri	:	Rezervor 1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_206361	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	S07180408734	☐ Corect	
Producator	:	SGB	☐ Corect	
Data fabricatiei	:	02.10.2007	☐ Corect	Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____

FISA VALIDARE INVENTAR

R1590 - 4 Oradea



Data: _____
Semnatura: _____