

FISA VALIDARE INVENTAR

R1591 - 5 Oradea



DATE GENERALE STATIE

Cod statie	:	R1591	Data verificarii	:	
Nume statie	:	5 Oradea	Persoana care verifica	:	
Numar distribuitoare	:	2			
Numar echipamente Sistem masura rezervoare	:			9	
Numar echipamente Rezervoare / sisteme asociate	:			25	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 2 - Pompa 1/2

Cod echipament	:	RO_237600	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	931120	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco SK700	☐ Corect	
Tip echipament	:	MPD 4/8 VR 3/6	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.11.2021	☐ Corect	
Numar produse	:	3	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	Apollo	☐ Corect	

DISTRIBUITOR 2 DIN 2 - Pompa 3/4

Cod echipament	:	RO_237601	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	931121	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco SK700	☐ Corect	
Tip echipament	:	MPD 4/8 VR 3/6	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.11.2021	☐ Corect	
Numar produse	:	3	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	Apollo	☐ Corect	

FISA VALIDARE INVENTAR

R1591 - 5 Oradea



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_206180	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 350R_	☐ Corect	
Tip echipament	:	Veeder-Root 350R	☐ Corect	
Data fabricatiei	:	31.12.2004	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_206181	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/1	☐ Corect	
Data fabricatiei	:	31.12.2004	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_206182	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/2	☐ Corect	
Data fabricatiei	:	31.12.2004	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_206183	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/3	☐ Corect	
Data fabricatiei	:	31.12.2004	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_206184	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1	☐ Corect	
Data fabricatiei	:	31.12.2004	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1591 - 5 Oradea



SONDA NIVEL 5 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_206185	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2/2	☐ Corect
Data fabricatiei	:	31.12.2004	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 6 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_206186	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2/3	☐ Corect
Data fabricatiei	:	31.12.2004	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_206187	☐ Corect
Serie echipament	:	101	☐ Corect
Producator	:	DELTA IMPEX	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	01.01.2000	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_206188	☐ Corect
Serie echipament	:	259	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica	☐ Corect
Data fabricatiei	:	04.09.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1591 - 5 Oradea



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 6

Rezervor	:	R1/1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Super 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_206189	☐ Corect	
Serie echipament	:	156	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2004	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	31.12.2004	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	31.12.2004	☐ Corect	

REZERVOR 2 DIN 6

Rezervor	:	R1/2 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Super 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_206192	☐ Corect	
Serie echipament	:	156	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2004	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	31.12.2004	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	31.12.2004	☐ Corect	

REZERVOR 3 DIN 6

Rezervor	:	R1/3 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/3 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_206195	☐ Corect	
Serie echipament	:	156	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2004	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	31.12.2004	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	31.12.2004	☐ Corect	

REZERVOR 4 DIN 6

Rezervor	:	R2/1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 MM100	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_206198	☐ Corect	
Serie echipament	:	157	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2004	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	31.12.2004	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	31.12.2004	☐ Corect	

REZERVOR 5 DIN 6

Rezervor	:	R2/2 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Super 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_206201	☐ Corect	

FISA VALIDARE INVENTAR

R1591 - 5 Oradea



Serie echipament	:	157	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.01.2004	☐ Corect
Capac Rezervor	:	unknown	☐ Corect
Data fabricatiei	:	31.12.2004	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	31.12.2004	☐ Corect

Observatii:

REZERVOR 6 DIN 6

Rezervor	:	R2/3 tricompartimentat	☐ Corect
Produs	:	R2/3 Diesel Std	☐ Corect
Cod echipament	:	RO_206204	☐ Corect
Serie echipament	:	157	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.01.2004	☐ Corect
Capac Rezervor	:	unknown	☐ Corect
Data fabricatiei	:	31.12.2004	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	31.12.2004	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 1

Sistem de detectie scurgeri	:	Rezervor 1 tricompartimentat	☐ Corect
Cod echipament	:	RO_206207	☐ Corect
Serie echipament	:	262329	☐ Corect
Producator	:	LECKANZEIGER	☐ Corect
Data fabricatiei	:	01.11.2004	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____

Funcție: _____

Data: _____

Semnatura: _____