

FISA VALIDARE INVENTAR

R1594 - 8 Bors



DATE GENERALE STATIE

Cod statie	: R1594	Data verificarii	:
Nume statie	: 8 Bors	Persoana care verifica	:
Numar distribuitoare	: 5		
Numar echipamente Sistem masura rezervoare	:	10	
Numar echipamente Rezervoare / sisteme asociate	:	32	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 5 - Pompa 1/2

Cod echipament	: RO_212017	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: D1045305	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Tokheim_Quantium 500T	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 1/2	☐ Corect	
Data fabricatiei	: 01.01.2010	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: WWC	☐ Corect	

DISTRIBUITOR 2 DIN 5 - Pompa 3/4

Cod echipament	: RO_212018	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: D1045286	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Tokheim_Quantium 500T	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 3/4	☐ Corect	
Data fabricatiei	: 01.01.2010	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: WWC	☐ Corect	

DISTRIBUITOR 3 DIN 5 - Pompa 5/6

Cod echipament	: RO_212019	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: D1008008	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Tokheim_Quantium 500T	☐ Corect	
Tip echipament	: HS 1-2	☐ Corect	
Numar dispenser	: Pompa 5/6	☐ Corect	
Data fabricatiei	: 01.01.2010	☐ Corect	
Numar produse	: 2	☐ Corect	
Debit	: 130 l/min	☐ Corect	Observatii:
Numar pistoale	: 4	☐ Corect	
Calculator pompa	: WWC	☐ Corect	

DISTRIBUITOR 4 DIN 5 - Pompa 7/8

Cod echipament	: RO_212020	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: D1014043	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Tokheim_Quantium 500T	☐ Corect	
Tip echipament	: HS 1-2	☐ Corect	
Numar dispenser	: Pompa 7/8	☐ Corect	
Data fabricatiei	: 01.01.2010	☐ Corect	
Numar produse	: 2	☐ Corect	
Debit	: 130 l/min	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1594 - 8 Bors



Numar pistoale	:	4	☐ Corect	_____
Calculator pompa	:	WWC	☐ Corect	_____

DISTRIBUITOR 5 DIN 5 - Pompa AdBlue 7/8

Cod echipament	:	RO_239743	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	943006/2022	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder Root SK700-2/ADBLUE	☐ Corect	

Tip echipament	:	Pompa Adblue Container	☐ Corect	_____
Numar dispenser	:	Pompa AdBlue 7/8	☐ Corect	_____
Data fabricatiei	:	24.12.2022	☐ Corect	_____
Numar produse	:	4	☐ Corect	_____
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	_____
Calculator pompa	:	WWC	☐ Corect	_____

FISA VALIDARE INVENTAR

R1594 - 8 Bors



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_212022	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 350R_	☐ Corect	
Tip echipament	:	Veeder-Root 350R	☐ Corect	
Data fabricatiei	:	01.09.2002	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 7

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_212023	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/1	☐ Corect	
Data fabricatiei	:	01.09.2002	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 7

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_212024	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/2	☐ Corect	
Data fabricatiei	:	01.09.2002	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 7

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_212025	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1	☐ Corect	
Data fabricatiei	:	01.09.2002	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 7

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_212026	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/2	☐ Corect	
Data fabricatiei	:	01.09.2002	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1594 - 8 Bors



SONDA NIVEL 5 DIN 7

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_212027	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3/1	☐ Corect
Data fabricatiei	:	01.09.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 6 DIN 7

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_212028	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3/2	☐ Corect
Data fabricatiei	:	01.09.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 7 DIN 7

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_212029	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R4	☐ Corect
Data fabricatiei	:	01.09.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_212030	☐ Corect
Serie echipament	:	4	☐ Corect
Producator	:	SC AMPLO	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	01.01.2008	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_212031	☐ Corect
Serie echipament	:	264	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica 4m	☐ Corect
Data fabricatiei	:	09.04.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1594 - 8 Bors



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 7

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_212032	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.09.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.09.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.09.2002	☐ Corect	

REZERVOR 2 DIN 7

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Extra 99	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_212035	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.09.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.09.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.09.2002	☐ Corect	

REZERVOR 3 DIN 7

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_212038	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.09.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.09.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.09.2002	☐ Corect	

REZERVOR 4 DIN 7

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Inactiv	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_212041	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.09.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.09.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.09.2002	☐ Corect	

REZERVOR 5 DIN 7

Rezervor	:	R3/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3/1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_212044	☐ Corect	

FISA VALIDARE INVENTAR

R1594 - 8 Bors



Serie echipament	:	FS	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.09.2002	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	01.09.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	01.09.2002	☐ Corect

Observatii:

REZERVOR 6 DIN 7

Rezervor	:	R3/2 bicompartimentat	☐ Corect
Produs	:	R3/2 Diesel Std	☐ Corect
Cod echipament	:	RO_212047	☐ Corect
Serie echipament	:	FS	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.09.2002	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	01.09.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	01.09.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

REZERVOR 7 DIN 7

Rezervor	:	R4 monocompartiment	☐ Corect
Produs	:	R4 Diesel Std	☐ Corect
Cod echipament	:	RO_212050	☐ Corect
Serie echipament	:	FS	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.09.2002	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	01.09.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	01.09.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 4

Sistem de detectie scurgeri	:	Rezervor 1 bicompartimentat	☐ Corect
Cod echipament	:	RO_212053	☐ Corect
Serie echipament	:	28079	☐ Corect
Producator	:	AFRISO	☐ Corect
Data fabricatiei	:	07.02.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 4

Sistem de detectie scurgeri	:	Rezervor 2 bicompartimentat	☐ Corect
Cod echipament	:	RO_212054	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	AFRISO	☐ Corect
Data fabricatiei	:	01.09.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 4

Sistem de detectie scurgeri	:	Rezervor 3 bicompartimentat	☐ Corect
Cod echipament	:	RO_212055	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	AFRISO	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

FISA VALIDARE INVENTAR

R1594 - 8 Bors



Data fabricatiei : 01.09.2002

☐ Corect

Observatii:

SISTEM DE DETECTIE SCURGERI 4 DIN 4

Sistem de detectie scurgeri : Rezervor 4 monocompartimentat

☐ Corect

Cod echipament : RO_212056

☐ Corect

Serie echipament :

☐ Corect

Producator : AFRISO

☐ Corect

Data fabricatiei : 01.09.2002

☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____

Functie: _____

Data: _____

Semnatura: _____