

FISA VALIDARE INVENTAR

R1605 - 2 Zalau



DATE GENERALE STATIE

Cod statie	:	R1605	Data verificarii	:	
Nume statie	:	2 Zalau	Persoana care verifica	:	
Numar distribuitoare	:	2			
Numar echipamente Sistem masura rezervoare	:			10	
Numar echipamente Rezervoare / sisteme asociate	:			31	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 2 - Pompa 1/2

Cod echipament	:	RO_234081	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	2027	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Nouvo Pignone	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2001	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:		☐ Corect	

DISTRIBUITOR 2 DIN 2 - Pompa 3/4

Cod echipament	:	RO_234082	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	2025	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Nouvo Pignone	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2001	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:		☐ Corect	

FISA VALIDARE INVENTAR

R1605 - 2 Zalau



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect
Cod echipament	:	RO_234084	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root 450R	☐ Corect
Tip echipament	:	Veeder-Root 450R	☐ Corect
Data fabricatiei	:	25.08.2011	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 1 DIN 7

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_234085	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R1/1	☐ Corect
Data fabricatiei	:	25.08.2011	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 2 DIN 7

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_234086	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R1/2	☐ Corect
Data fabricatiei	:	25.08.2011	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 3 DIN 7

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_234087	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R1/3	☐ Corect
Data fabricatiei	:	25.08.2011	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 4 DIN 7

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_234088	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2/1	☐ Corect
Data fabricatiei	:	25.08.2011	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1605 - 2 Zalau



SONDA NIVEL 5 DIN 7

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_234089	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2/2	☐ Corect
Data fabricatiei	:	25.08.2011	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 6 DIN 7

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_234090	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3/1	☐ Corect
Data fabricatiei	:	25.08.2011	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 7 DIN 7

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_234091	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3/2	☐ Corect
Data fabricatiei	:	25.08.2011	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_234092	☐ Corect
Serie echipament	:	135	☐ Corect
Producator	:	AMPLO	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	01.01.2008	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_234093	☐ Corect
Serie echipament	:	122	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica 4m	☐ Corect
Data fabricatiei	:	05.06.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1605 - 2 Zalau



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 7

Rezervor	:	R1/1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_234094	☐ Corect	
Serie echipament	:	369/1	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.07.2002	☐ Corect	Observatii:
Capac Rezervor	:	FIBRALITE FL90	☐ Corect	
Data fabricatiei	:	01.07.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.07.2002	☐ Corect	

REZERVOR 2 DIN 7

Rezervor	:	R1/2 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_234097	☐ Corect	
Serie echipament	:	369/2	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.07.2002	☐ Corect	Observatii:
Capac Rezervor	:	FIBRALITE FL90	☐ Corect	
Data fabricatiei	:	01.07.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.07.2002	☐ Corect	

REZERVOR 3 DIN 7

Rezervor	:	R1/3 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/3 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_234100	☐ Corect	
Serie echipament	:	369/2	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.07.2002	☐ Corect	Observatii:
Capac Rezervor	:	FIBRALITE FL90	☐ Corect	
Data fabricatiei	:	01.07.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.07.2002	☐ Corect	

REZERVOR 4 DIN 7

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Extra 99	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_234103	☐ Corect	
Serie echipament	:	370/1	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.07.2002	☐ Corect	Observatii:
Capac Rezervor	:	FIBRALITE FL90	☐ Corect	
Data fabricatiei	:	01.07.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.07.2002	☐ Corect	

REZERVOR 5 DIN 7

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_234106	☐ Corect	

FISA VALIDARE INVENTAR

R1605 - 2 Zalau



Serie echipament	:	370/2	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.07.2002	☐ Corect
Capac Rezervor	:	FIBRALITE FL90	☐ Corect
Data fabricatiei	:	01.07.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	01.07.2002	☐ Corect

Observatii:

REZERVOR 6 DIN 7

Rezervor	:	R3/1 bicompartimentat	☐ Corect
Produs	:	R3/1 Diesel Std	☐ Corect
Cod echipament	:	RO_234109	☐ Corect
Serie echipament	:	371/1	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.07.2002	☐ Corect
Capac Rezervor	:	FIBRALITE FL90	☐ Corect
Data fabricatiei	:	01.07.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	01.07.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

REZERVOR 7 DIN 7

Rezervor	:	R3/2 bicompartimentat	☐ Corect
Produs	:	R3/2 Diesel Extra	☐ Corect
Cod echipament	:	RO_234112	☐ Corect
Serie echipament	:	371/2	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.07.2002	☐ Corect
Capac Rezervor	:	FIBRALITE FL90	☐ Corect
Data fabricatiei	:	01.07.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	01.07.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 3

Sistem de detectie scurgeri	:	Rezervor 1 tricompartimentat	☐ Corect
Cod echipament	:	RO_234115	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	AFRISO	☐ Corect
Data fabricatiei	:	01.07.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 3

Sistem de detectie scurgeri	:	Rezervor 2 bicompartimentat	☐ Corect
Cod echipament	:	RO_234116	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	AFRISO	☐ Corect
Data fabricatiei	:	01.07.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 3

Sistem de detectie scurgeri	:	Rezervor 3 bicompartimentat	☐ Corect
Cod echipament	:	RO_234117	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	AFRISO	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

FISA VALIDARE INVENTAR

R1605 - 2 Zalau



Data fabricatiei : 01.07.2002

[] Corect

Observatii:

VERIFICARE FINALA

Nume: _____

Funcție: _____

Data: _____

Semnatura: _____