

FISA VALIDARE INVENTAR

R1606 - 3 Simleu Silvaniei



DATE GENERALE STATIE

Cod statie	: R1606	Data verificarii	:
Nume statie	: 3 Simleu Silvaniei	Persoana care verifica	:
Numar distribuitoare	: 6		
Numar echipamente Sistem masura rezervoare	:	8	
Numar echipamente Rezervoare / sisteme asociate	:	18	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 6 - Pompa 1/2

Cod echipament	: RO_239202	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 946067/2023	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4 (DM)	☐ Corect	
Numar dispenser	: Pompa 1/2	☐ Corect	
Data fabricatiei	: 24.02.2023	☐ Corect	
Numar produse	: 2	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 4	☐ Corect	
Calculator pompa	: TQC	☐ Corect	

DISTRIBUITOR 2 DIN 6 - Pompa 3/4

Cod echipament	: RO_239203	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 946066/2023	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 3/4	☐ Corect	
Data fabricatiei	: 24.02.2023	☐ Corect	
Numar produse	: 2	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 4	☐ Corect	
Calculator pompa	: TQC	☐ Corect	

DISTRIBUITOR 3 DIN 6 - Pompa 5/6

Cod echipament	: RO_239204	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 946065/2023	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 5/6	☐ Corect	
Data fabricatiei	: 24.02.2023	☐ Corect	
Numar produse	: 1	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 1	☐ Corect	
Calculator pompa	: TQC	☐ Corect	

DISTRIBUITOR 4 DIN 6 - Pompa Adblue 5/6

Cod echipament	: RO_239205	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 946068/2023	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root_SK700-2/ADBLUE	☐ Corect	
Tip echipament	: Adblue 5/6	☐ Corect	
Numar dispenser	: Pompa Adblue 5/6	☐ Corect	
Data fabricatiei	: 24.02.2023	☐ Corect	
Numar produse	: 1	☐ Corect	

FISA VALIDARE INVENTAR

R1606 - 3 Simleu Silvaniei



Debit	:	130 l/min	☐ Corect
Numar pistoale	:	1	☐ Corect
Calculator pompa	:	TQC	☐ Corect

Observatii:

DISTRIBUITOR 5 DIN 6 - Pompa Adblue 3/4

Cod echipament	:	RO_239206	☐ Corect
Serie echipament	:	946069/2023	☐ Corect
Producator	:	Gilbarco Veeder-Root_SK700-2/ADBLUE	

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

☐ Corect

Tip echipament	:	Adblue 3/4	☐ Corect
Numar dispenser	:	Pompa Adblue 3/4	☐ Corect
Data fabricatiei	:	24.02.2023	☐ Corect
Numar produse	:	1	☐ Corect
Debit	:	130 l/min	☐ Corect
Numar pistoale	:	1	☐ Corect
Calculator pompa	:	TQC	☐ Corect

Observatii:

DISTRIBUITOR 6 DIN 6 - Pompa Adblue 1/2

Cod echipament	:	RO_239207	☐ Corect
Serie echipament	:	946070/2023	☐ Corect
Producator	:	Gilbarco Veeder-Root_SK700-2/ADBLUE	

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

☐ Corect

Tip echipament	:	Adblue 1/2	☐ Corect
Numar dispenser	:	Pompa Adblue 1/2	☐ Corect
Data fabricatiei	:	24.02.2023	☐ Corect
Numar produse	:	1	☐ Corect
Debit	:	130 l/min	☐ Corect
Numar pistoale	:	1	☐ Corect
Calculator pompa	:	TQC	☐ Corect

Observatii:

FISA VALIDARE INVENTAR

R1606 - 3 Simleu Silvaniei



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_239209	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	ProGauge	☐ Corect	
Tip echipament	:	MagLink LX 4 ProGauge	☐ Corect	
Data fabricatiei	:	30.05.2023	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_239210	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/1	☐ Corect	
Data fabricatiei	:	30.05.2023	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_239211	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/2	☐ Corect	
Data fabricatiei	:	30.05.2023	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_239212	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1	☐ Corect	
Data fabricatiei	:	30.05.2023	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_239213	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/2	☐ Corect	
Data fabricatiei	:	30.05.2023	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1606 - 3 Simleu Silvaniei



SONDA NIVEL 5 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_239214	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3	☐ Corect
Data fabricatiei	:	30.05.2023	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_239215	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	30.05.2023	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_239216	☐ Corect
Serie echipament	:	121	☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica 4m	☐ Corect
Data fabricatiei	:	30.05.2023	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1606 - 3 Simleu Silvaniei



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 5

Rezervor	:	R1/2 bicompartimentat	☐ Corect
Produs	:	R1/2 Extra 99	☐ Corect
Cod echipament	:	RO_239217	☐ Corect
Serie echipament	:	FS	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	30.05.2023	☐ Corect
Capac Rezervor	:	unknown	☐ Corect
Data fabricatiei	:	30.05.2023	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	30.05.2023	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

REZERVOR 2 DIN 5

Rezervor	:	R1/2 bicompartimentat	☐ Corect
Produs	:	R1/2 Extra 99	☐ Corect
Cod echipament	:	RO_239220	☐ Corect
Serie echipament	:	FS	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	30.05.2023	☐ Corect
Capac Rezervor	:	unknown	☐ Corect
Data fabricatiei	:	30.05.2023	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	30.05.2023	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

REZERVOR 3 DIN 5

Rezervor	:	R2/1 bicompartimentat	☐ Corect
Produs	:	R2/1 Diesel Extra	☐ Corect
Cod echipament	:	RO_239223	☐ Corect
Serie echipament	:	FS	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	30.05.2023	☐ Corect
Capac Rezervor	:	unknown	☐ Corect
Data fabricatiei	:	30.05.2023	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	30.05.2023	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

REZERVOR 4 DIN 5

Rezervor	:	R2/2 bicompartimentat	☐ Corect
Produs	:	R2/2 Diesel Std	☐ Corect
Cod echipament	:	RO_239226	☐ Corect
Serie echipament	:	FS	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	30.05.2023	☐ Corect
Capac Rezervor	:	unknown	☐ Corect
Data fabricatiei	:	30.05.2023	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

REZERVOR 5 DIN 5

Rezervor	:	R3 monocompartimentat	☐ Corect
Produs	:	R3 Adblue	☐ Corect
Cod echipament	:	RO_239229	☐ Corect
Serie echipament	:	FS	☐ Corect
Producator	:	unknown	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

FISA VALIDARE INVENTAR

R1606 - 3 Simleu Silvaniei



Data fabricatiei : 30.05.2023
Capac Rezervor : unknown
Data fabricatiei : 30.05.2023

[] Corect
[] Corect
[] Corect

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____