

FISA VALIDARE INVENTAR

R1607 - 4 Jibou



DATE GENERALE STATIE

Cod statie	:	R1607	Data verificarii	:	
Nume statie	:	4 Jibou	Persoana care verifica	:	
Numar distribuitoare	:	3			
Numar echipamente Sistem masura rezervoare	:			9	
Numar echipamente Rezervoare / sisteme asociate	:			27	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 3 - Pompa 1/2

Cod echipament	:	RO_233757	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D0045096	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2000	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:		☐ Corect	

DISTRIBUITOR 2 DIN 3 - Pompa 3/4

Cod echipament	:	RO_233758	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D0045094	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2000	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:		☐ Corect	

DISTRIBUITOR 3 DIN 3 - Pompa 5/6

Cod echipament	:	RO_233759	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D0103055	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim	☐ Corect	
Tip echipament	:	HS 1-2	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	01.01.2001	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	130 l/min	☐ Corect	Observatii:
Numar pistoale	:	2	☐ Corect	
Calculator pompa	:		☐ Corect	

FISA VALIDARE INVENTAR

R1607 - 4 Jibou



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_233761	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	ELECTRONIC	☐ Corect	_____
Tip echipament	:	ELECTRONIC OPTILEVEL		_____
		Optilevel C104M	☐ Corect	
Data fabricatiei	:	01.04.2009	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_233762	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root	☐ Corect	_____
Tip echipament	:	Sonda R1/1	☐ Corect	_____
Data fabricatiei	:	01.04.2009	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_233763	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root	☐ Corect	_____
Tip echipament	:	Sonda R1/2	☐ Corect	_____
Data fabricatiei	:	01.04.2009	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_233764	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root	☐ Corect	_____
Tip echipament	:	Sonda R2/1	☐ Corect	_____
Data fabricatiei	:	01.04.2009	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_233765	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root	☐ Corect	_____
Tip echipament	:	Sonda R2/2	☐ Corect	_____
Data fabricatiei	:	01.04.2009	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1607 - 4 Jibou



SONDA NIVEL 5 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_233766	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2/3	☐ Corect
Data fabricatiei	:	01.04.2009	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 6 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_233767	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3	☐ Corect
Data fabricatiei	:	01.04.2009	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_233768	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	30.04.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_233769	☐ Corect
Serie echipament	:	120	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica 4m	☐ Corect
Data fabricatiei	:	05.06.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1607 - 4 Jibou



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 6

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Extra 99	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_233770	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	30.04.2001	☐ Corect	Observatii:
Capac Rezervor	:	FIBRALITE FL76	☐ Corect	
Data fabricatiei	:	30.04.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	30.04.2001	☐ Corect	

REZERVOR 2 DIN 6

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_233773	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	30.04.2001	☐ Corect	Observatii:
Capac Rezervor	:	FIBRALITE FL76	☐ Corect	
Data fabricatiei	:	30.04.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	30.04.2001	☐ Corect	

REZERVOR 3 DIN 6

Rezervor	:	R2/1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_233776	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	30.04.2001	☐ Corect	Observatii:
Capac Rezervor	:	FIBRALITE FL76	☐ Corect	
Data fabricatiei	:	30.04.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	30.04.2001	☐ Corect	

REZERVOR 4 DIN 6

Rezervor	:	R2/2 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_233779	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	30.04.2001	☐ Corect	Observatii:
Capac Rezervor	:	FIBRALITE FL76	☐ Corect	
Data fabricatiei	:	30.04.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	30.04.2001	☐ Corect	

REZERVOR 5 DIN 6

Rezervor	:	R2/3 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/3 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_233782	☐ Corect	

FISA VALIDARE INVENTAR

R1607 - 4 Jibou



Serie echipament	:	FS	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	30.04.2001	☐ Corect
Capac Rezervor	:	FIBRALITE FL76	☐ Corect
Data fabricatiei	:	30.04.2001	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	30.04.2001	☐ Corect

Observatii:

REZERVOR 6 DIN 6

Rezervor	:	R3 monocompartimentat	☐ Corect
Produs	:	R3 Diesel Std	☐ Corect
Cod echipament	:	RO_233785	☐ Corect
Serie echipament	:	FS	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	30.04.2001	☐ Corect
Capac Rezervor	:	unknown	☐ Corect
Data fabricatiei	:	30.04.2001	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	30.04.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 3

Sistem de detectie scurgeri	:	Rezervor 1 bicompartimentat	☐ Corect
Cod echipament	:	RO_233788	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	30.04.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 3

Sistem de detectie scurgeri	:	Rezervor 2 tricompartimentat	☐ Corect
Cod echipament	:	RO_233789	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	30.04.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 3

Sistem de detectie scurgeri	:	Rezervor 3 monocompartimentat	☐ Corect
Cod echipament	:	RO_233790	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	30.04.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____