

FISA VALIDARE INVENTAR

R1609 - 6 Ileanda



DATE GENERALE STATIE

Cod statie	: R1609	Data verificarii	:
Nume statie	: 6 Ileanda	Persoana care verifica	:
Numar distribuitoare	: 4		
Numar echipamente Sistem masura rezervoare	:	6	
Numar echipamente Rezervoare / sisteme asociate	:	15	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 4 - Pompa 1/2

Cod echipament	: RO_234461	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: D1651026	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Tokheim_Quantium 510	☐ Corect	
Tip echipament	: MPD 2/4 VR 1/2	☐ Corect	
Numar dispenser	: Pompa 1/2	☐ Corect	
Data fabricatiei	: 01.01.2016	☐ Corect	
Numar produse	: 2	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 4	☐ Corect	
Calculator pompa	: WWC	☐ Corect	

DISTRIBUITOR 2 DIN 4 - Pompa 3/4

Cod echipament	: RO_234462	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: D1651175	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Tokheim_Quantium 510	☐ Corect	
Tip echipament	: HS 1-2	☐ Corect	
Numar dispenser	: Pompa 3/4	☐ Corect	
Data fabricatiei	: 01.01.2016	☐ Corect	
Numar produse	: 1	☐ Corect	
Debit	: 130 l/min	☐ Corect	Observatii:
Numar pistoale	: 2	☐ Corect	
Calculator pompa	: WWC	☐ Corect	

DISTRIBUITOR 3 DIN 4 - Pompa 5/6

Cod echipament	: RO_234463	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: D1651025	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Tokheim_Quantium 510	☐ Corect	
Tip echipament	: MPD 2/4 VR 1/2	☐ Corect	
Numar dispenser	: Pompa 5/6	☐ Corect	
Data fabricatiei	: 01.01.2016	☐ Corect	
Numar produse	: 2	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 4	☐ Corect	
Calculator pompa	: WWC	☐ Corect	

DISTRIBUITOR 4 DIN 4 - Pompa 7/8

Cod echipament	: RO_234464	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: D1651020	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Tokheim_Quantium 510	☐ Corect	
Tip echipament	: HS MPD 2/4	☐ Corect	
Numar dispenser	: Pompa 7/8	☐ Corect	
Data fabricatiei	: 01.01.2016	☐ Corect	
Numar produse	: 2	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1609 - 6 Ileanda



Numar pistoale	:	4	☐ Corect	_____
Calculator pompa	:	WWC	☐ Corect	_____

FISA VALIDARE INVENTAR

R1609 - 6 Ileanda



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_234466	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	ELECTRONIC_	☐ Corect	
Tip echipament	:	ELECTRONIC OPTILEVEL		
		Optilevel C104M	☐ Corect	
Data fabricatiei	:	20.10.2008	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_234467	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1	☐ Corect	
Data fabricatiei	:	20.10.2008	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_234468	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2	☐ Corect	
Data fabricatiei	:	20.10.2008	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_234469	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R3	☐ Corect	
Data fabricatiei	:	20.10.2008	☐ Corect	Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_234470	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Mecaf_	☐ Corect	
Tip echipament	:	Vas etalon	☐ Corect	
Data fabricatiei	:	01.12.1997	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1609 - 6 Ileanda



RIGLA GRADATA 1 DIN 1

Echipament : Rigla Gradata
Cod echipament : RO_234471
Serie echipament : 123
Producator : Mecaf_
Tip echipament : Rigla metalica 4m
Data fabricatiei : 05.06.2019

☐ Corect
☐ Corect
☐ Corect
☐ Corect
☐ Corect
☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1609 - 6 Ileanda



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 3

Rezervor	:	R1 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_234472	☐ Corect	
Serie echipament	:	348	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.06.1997	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	01.06.1997	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.06.1997	☐ Corect	

REZERVOR 2 DIN 3

Rezervor	:	R2 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_234475	☐ Corect	
Serie echipament	:	349	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.06.1997	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	01.06.1997	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.06.1997	☐ Corect	

REZERVOR 3 DIN 3

Rezervor	:	R3 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_234478	☐ Corect	
Serie echipament	:	350	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.06.1997	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	
Data fabricatiei	:	01.06.1997	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.06.1997	☐ Corect	

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 3

Sistem de detectie scurgeri	:	Rezervor 1 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_234481	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	SGB	☐ Corect	
Data fabricatiei	:	01.04.1985	☐ Corect	Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 3

Sistem de detectie scurgeri	:	Rezervor 2 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_234482	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	SGB	☐ Corect	

FISA VALIDARE INVENTAR

R1609 - 6 Ileanda



Data fabricatiei : 01.04.1985 [] Corect

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 3

Sistem de detectie scurgeri : Rezervor 3 monocompartimentat [] Corect
Cod echipament : RO_234483 [] Corect
Serie echipament : [] Corect
Producator : SGB [] Corect
Data fabricatiei : 01.04.1985 [] Corect

[] Datele sunt corecte [] Necesita modificari

Valori corectate / informatii de pe placuta:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____