

FISA VALIDARE INVENTAR

R1639 - 2 Negresti Oas



DATE GENERALE STATIE

Cod statie	:	R1639	Data verificarii	:	
Nume statie	:	2 Negresti Oas	Persoana care verifica	:	
Numar distribuitoare	:	3			
Numar echipamente Sistem masura rezervoare	:			9	
Numar echipamente Rezervoare / sisteme asociate	:			24	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 3 - Pompa 1/2

Cod echipament	:	RO_235674	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	701099	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2020	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:		☐ Corect	

DISTRIBUITOR 2 DIN 3 - Pompa 3/4

Cod echipament	:	RO_235675	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	701097	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2020	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:		☐ Corect	

DISTRIBUITOR 3 DIN 3 - Pompa 5/6

Cod echipament	:	RO_235676	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	701114	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root	☐ Corect	
Tip echipament	:	HS 1-2	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	01.01.2020	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	130 l/min	☐ Corect	Observatii:
Numar pistoale	:	2	☐ Corect	
Calculator pompa	:		☐ Corect	

FISA VALIDARE INVENTAR

R1639 - 2 Negresti Oas



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_229952	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 450R PLUS	☐ Corect	
Tip echipament	:	Veeder-Root 450R PLUS	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_229953	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/1	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_229954	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/2	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_229955	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/3	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_229956	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1639 - 2 Negresti Oas



SONDA NIVEL 5 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_229957	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2/2	☐ Corect
Data fabricatiei	:	16.08.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 6 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_229958	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2/3	☐ Corect
Data fabricatiei	:	16.08.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_229959	☐ Corect
Serie echipament	:	FS	☐ Corect
Producator	:	Mecaf	☐ Corect
Tip echipament	:	Vas etalon Vas etalon	
		20L	☐ Corect
Data fabricatiei	:	01.01.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_229960	☐ Corect
Serie echipament	:	949	☐ Corect
Producator	:	Mecaf	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	24.04.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1639 - 2 Negresti Oas



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 6

Rezervor	:	R1/1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_229961	☐ Corect	
Serie echipament	:	ACIS0104A	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.1999	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	30.01.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	30.01.2002	☐ Corect	

REZERVOR 2 DIN 6

Rezervor	:	R1/2 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_229964	☐ Corect	
Serie echipament	:	ACIS0104B	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.1999	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	30.01.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	30.01.2002	☐ Corect	

REZERVOR 3 DIN 6

Rezervor	:	R1/3 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/3 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_229967	☐ Corect	
Serie echipament	:	ACIS0104C	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.1999	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	30.01.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	30.01.2002	☐ Corect	

REZERVOR 4 DIN 6

Rezervor	:	R2/1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_229970	☐ Corect	
Serie echipament	:	ACIS0105A	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.1999	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	30.01.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	30.01.2002	☐ Corect	

REZERVOR 5 DIN 6

Rezervor	:	R2/2 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_229973	☐ Corect	

FISA VALIDARE INVENTAR

R1639 - 2 Negresti Oas



Serie echipament	:	ACIS0104B	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.01.1999	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	30.01.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	30.01.2002	☐ Corect

Observatii:

REZERVOR 6 DIN 6

Rezervor	:	R2/3 tricompartimentat	☐ Corect
Produs	:	R2/3 Extra 99	☐ Corect
Cod echipament	:	RO_229976	☐ Corect
Serie echipament	:	ACIS0104C	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.01.1999	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	30.01.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	30.01.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____