

FISA VALIDARE INVENTAR

R1640 - 3 Satu Mare



DATE GENERALE STATIE

Cod statie	:	R1640	Data verificarii	:	
Nume statie	:	3 Satu Mare	Persoana care verifica	:	
Numar distribuitoare	:	2			
Numar echipamente Sistem masura rezervoare	:			9	
Numar echipamente Rezervoare / sisteme asociate	:			26	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 2 - Pompa 1/2

Cod echipament	:	RO_238803	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	943236	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root SK700-2	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	24.11.2022	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:		☐ Corect	

DISTRIBUITOR 2 DIN 2 - Pompa 3/4

Cod echipament	:	RO_238804	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	943237	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root SK700-2	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	24.11.2022	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:		☐ Corect	

FISA VALIDARE INVENTAR

R1640 - 3 Satu Mare



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_230045	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 450PLUS	☐ Corect	
Tip echipament	:	Veeder-Root 450PLUS	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_230046	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/1	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_230047	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/2	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_230048	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/3	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 6

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_230049	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1	☐ Corect	
Data fabricatiei	:	16.08.2019	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1640 - 3 Satu Mare



SONDA NIVEL 5 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_230050	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2/2	☐ Corect
Data fabricatiei	:	16.08.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 6 DIN 6

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_230051	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2/3	☐ Corect
Data fabricatiei	:	16.08.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_230052	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	30.11.2004	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_236127	☐ Corect
Serie echipament	:	957	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 4m	☐ Corect
Data fabricatiei	:	19.12.2020	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1640 - 3 Satu Mare



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 6

Rezervor	:	R1/1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_230054	☐ Corect	
Serie echipament	:	R61B-04A	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2004	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	30.11.2004	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	30.11.2004	☐ Corect	

REZERVOR 2 DIN 6

Rezervor	:	R1/2 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_230057	☐ Corect	
Serie echipament	:	R61B-04B	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2004	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	30.11.2004	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	30.11.2004	☐ Corect	

REZERVOR 3 DIN 6

Rezervor	:	R1/3 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/3 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_230060	☐ Corect	
Serie echipament	:	R61B-04C	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2004	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	30.11.2004	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	30.11.2004	☐ Corect	

REZERVOR 4 DIN 6

Rezervor	:	R2/1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_230063	☐ Corect	
Serie echipament	:	R51B-04A	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2004	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	30.11.2004	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	30.11.2004	☐ Corect	

REZERVOR 5 DIN 6

Rezervor	:	R2/2 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Extra 99	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_230066	☐ Corect	

FISA VALIDARE INVENTAR

R1640 - 3 Satu Mare



Serie echipament	:	R51B-04B	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.01.2004	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	30.11.2004	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	30.11.2004	☐ Corect

Observatii:

REZERVOR 6 DIN 6

Rezervor	:	R2/3 tricompartimentat	☐ Corect
Produs	:	R2/3 Diesel Extra	☐ Corect
Cod echipament	:	RO_230069	☐ Corect
Serie echipament	:	R51B-04C	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.01.2004	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	30.11.2004	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	30.11.2004	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 2

Sistem de detectie scurgeri	:	Rezervor 1 tricompartimentat	☐ Corect
Cod echipament	:	RO_230072	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	30.11.2004	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 2

Sistem de detectie scurgeri	:	Rezervor 2 tricompartimentat	☐ Corect
Cod echipament	:	RO_230073	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	30.11.2004	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____