

FISA VALIDARE INVENTAR

R1642 - 8 Satu Mare



DATE GENERALE STATIE

Cod statie	:	R1642	Data verificarii	:	
Nume statie	:	8 Satu Mare	Persoana care verifica	:	
Numar distribuitoare	:	3			
Numar echipamente Sistem masura rezervoare	:			7	
Numar echipamente Rezervoare / sisteme asociate	:			22	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 3 - Pompa 1/2

Cod echipament	:	RO_230251	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	400666	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	DRESSER WAYNE PIGNONE	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4 (DM)	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2006	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:		☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	DPX-F2	☐ Corect	

DISTRIBUITOR 2 DIN 3 - Pompa 3/4

Cod echipament	:	RO_230252	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	400589	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	DRESSER WAYNE PIGNONE	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2006	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	DPX-F2	☐ Corect	

DISTRIBUITOR 3 DIN 3 - Pompa 5/6

Cod echipament	:	RO_230253	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	306351	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	DRESSER WAYNE PIGNONE	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	01.01.2005	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	DPX-F2	☐ Corect	

FISA VALIDARE INVENTAR

R1642 - 8 Satu Mare



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_230255	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	ELECTRONIC_	☐ Corect	
Tip echipament	:	ELECTRONIC OPTILEVEL		
		Optilevel C104M	☐ Corect	
Data fabricatiei	:	21.11.2007	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_230256	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/1	☐ Corect	
Data fabricatiei	:	21.11.2007	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_230257	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/2	☐ Corect	
Data fabricatiei	:	21.11.2007	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_230258	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1	☐ Corect	
Data fabricatiei	:	21.11.2007	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_230259	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/2	☐ Corect	
Data fabricatiei	:	21.11.2007	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1642 - 8 Satu Mare



SONDA NIVEL 5 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_230260	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2/3	☐ Corect
Data fabricatiei	:	21.11.2007	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_236128	☐ Corect
Serie echipament	:	984	☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	19.12.2020	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1642 - 8 Satu Mare



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 5

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_230262	☐ Corect	
Serie echipament	:	570	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2007	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	21.11.2007	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	21.11.2007	☐ Corect	

REZERVOR 2 DIN 5

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 OMV Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_230265	☐ Corect	
Serie echipament	:	570	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2007	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	21.11.2007	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	21.11.2007	☐ Corect	

REZERVOR 3 DIN 5

Rezervor	:	R2/1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 OMV Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_230268	☐ Corect	
Serie echipament	:	584	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2007	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	21.11.2007	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	21.11.2007	☐ Corect	

REZERVOR 4 DIN 5

Rezervor	:	R2/2 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 MM 100+	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_230271	☐ Corect	
Serie echipament	:	584	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2007	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	21.11.2007	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	21.11.2007	☐ Corect	

REZERVOR 5 DIN 5

Rezervor	:	R2/3 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/3 MM 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_230274	☐ Corect	

FISA VALIDARE INVENTAR

R1642 - 8 Satu Mare



Serie echipament	:	584	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.01.2007	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	21.11.2007	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	21.11.2007	☐ Corect

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 2

Sistem de detectie scurgeri	:	Rezervor 1 bicompartimentat	☐ Corect
Cod echipament	:	RO_230277	☐ Corect
Serie echipament	:	298538	☐ Corect
Producator	:	LECKANZEIGER	☐ Corect
Data fabricatiei	:	21.11.2007	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 2

Sistem de detectie scurgeri	:	Rezervor 2 tricompartimentat	☐ Corect
Cod echipament	:	RO_230278	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	LECKANZEIGER	☐ Corect
Data fabricatiei	:	21.11.2007	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____