

FISA VALIDARE INVENTAR

R1649 - 16 Livada



DATE GENERALE STATIE

Cod statie	:	R1649	Data verificarii	:	
Nume statie	:	16 Livada	Persoana care verifica	:	
Numar distribuitoare	:	3			
Numar echipamente Sistem masura rezervoare	:			6	
Numar echipamente Rezervoare / sisteme asociate	:			15	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 3 - Pompa 1/2

Cod echipament	:	RO_230761	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D1504204	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantium 510	☐ Corect	
Tip echipament	:	MPD 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2015	☐ Corect	
Numar produse	:	2	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	4	☐ Corect	
Calculator pompa	:	TQC	☐ Corect	

DISTRIBUITOR 2 DIN 3 - Pompa 3/4

Cod echipament	:	RO_230762	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D1504205	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantium 510	☐ Corect	
Tip echipament	:	MPD 2/4 VR 1/2	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2015	☐ Corect	
Numar produse	:	2	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	4	☐ Corect	
Calculator pompa	:	TQC	☐ Corect	

DISTRIBUITOR 3 DIN 3 - Pompa 5/6

Cod echipament	:	RO_230763	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D1504141	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantium 510	☐ Corect	
Tip echipament	:	HS 1-2	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	01.01.2015	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	130 l/min	☐ Corect	Observatii:
Numar pistoale	:	2	☐ Corect	
Calculator pompa	:	TQC	☐ Corect	

FISA VALIDARE INVENTAR

R1649 - 16 Livada



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_230765	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	ELECTRONIC_	☐ Corect	
Tip echipament	:	ELECTRONIC OPTILEVEL		
		Optilevel C104M	☐ Corect	
Data fabricatiei	:	20.10.2008	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_230766	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1	☐ Corect	
Data fabricatiei	:	20.10.2008	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_230767	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2	☐ Corect	
Data fabricatiei	:	20.10.2008	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 3

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_230768	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R3	☐ Corect	
Data fabricatiei	:	20.10.2008	☐ Corect	Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_230769	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	86	☐ Corect	
Producator	:	DELTA IMPEX	☐ Corect	
Tip echipament	:	Vas etalon	☐ Corect	
Data fabricatiei	:	01.01.2008	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1649 - 16 Livada



RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_230770	☐ Corect
Serie echipament	:	916	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 4m	☐ Corect
Data fabricatiei	:	24.04.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1649 - 16 Livada



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 3

Rezervor	:	R1 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_230771	☐ Corect	
Serie echipament	:	517	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	20.10.2003	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	20.10.2003	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	20.10.2003	☐ Corect	

REZERVOR 2 DIN 3

Rezervor	:	R2 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_230774	☐ Corect	
Serie echipament	:	518	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	20.10.2003	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	20.10.2003	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	20.10.2003	☐ Corect	

REZERVOR 3 DIN 3

Rezervor	:	R3 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_230777	☐ Corect	
Serie echipament	:	519	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	20.10.2003	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	20.10.2003	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	20.10.2003	☐ Corect	

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 3

Sistem de detectie scurgeri	:	Rezervor 1 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_230780	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	SGB	☐ Corect	
Data fabricatiei	:	20.10.2003	☐ Corect	Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 3

Sistem de detectie scurgeri	:	Rezervor 2 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_230781	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	SGB	☐ Corect	

FISA VALIDARE INVENTAR

R1649 - 16 Livada



Data fabricatiei : 20.10.2003

☐ Corect

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 3

Sistem de detectie scurgeri : Rezervor 3 monocompartimentat

☐ Corect

Cod echipament : RO_230782

☐ Corect

Serie echipament :

☐ Corect

Producator : SGB

☐ Corect

Data fabricatiei : 20.10.2003

☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

VERIFICARE FINALA

Nume: _____

Functie: _____

Data: _____

Semnatura: _____