

FISA VALIDARE INVENTAR

R1742 - MPP Alba Iulia



DATE GENERALE STATIE

Cod statie	:	R1742	Data verificarii	:	
Nume statie	:	MPP Alba Iulia	Persoana care verifica	:	
Numar distribuitoare	:	4			
Numar echipamente Sistem masura rezervoare	:			7	
Numar echipamente Rezervoare / sisteme asociate	:			19	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 4 - Pompa 7

Cod echipament	:	RO_013898	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	679429	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	:	HS 1-1	☐ Corect	
Numar dispenser	:	Pompa 7	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	130 l/min	☐ Corect	Observatii:
Numar pistoale	:	1	☐ Corect	
Calculator pompa	:	SK700	☐ Corect	

DISTRIBUITOR 2 DIN 4 - Pompa 5/6

Cod echipament	:	RO_013899	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	679426	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	SK700	☐ Corect	

DISTRIBUITOR 3 DIN 4 - Pompa 3/4

Cod echipament	:	RO_013900	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	679428	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	SK700	☐ Corect	

DISTRIBUITOR 4 DIN 4 - Pompa 1/2

Cod echipament	:	RO_013901	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	679427	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1742 - MPP Alba Iulia



Numar pistoale	:	8	☐ Corect	_____
Calculator pompa	:	SK700	☐ Corect	_____

FISA VALIDARE INVENTAR

R1742 - MPP Alba Iulia



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013903	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	*70743840505016	☐ Corect	
Producator	:	Veeder-Root 350R_	☐ Corect	
Tip echipament	:	Veeder-Root 350R	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013904	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	4256	☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013905	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	3834	☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013906	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	3979	☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R3/1	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_013907	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	3979	☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R3/2	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1742 - MPP Alba Iulia



VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_013908	☐ Corect
Serie echipament	:	130	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	01.10.2010	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_013909	☐ Corect
Serie echipament	:	646	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	01.10.2010	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1742 - MPP Alba Iulia



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 4

Rezervor	:	R1 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013910	☐ Corect	
Serie echipament	:	78	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	

REZERVOR 2 DIN 4

Rezervor	:	R2 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013913	☐ Corect	
Serie echipament	:	79	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	

REZERVOR 3 DIN 4

Rezervor	:	R3/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3/1 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013916	☐ Corect	
Serie echipament	:	80	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	

REZERVOR 4 DIN 4

Rezervor	:	R3/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3/2 Extra 99	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_013919	☐ Corect	
Serie echipament	:	80	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 3

FISA VALIDARE INVENTAR

R1742 - MPP Alba Iulia



Sistem de detectie scurgeri : Rezervor 1 monocompartimentat ☐ Corect
Cod echipament : RO_013922 ☐ Corect
Serie echipament : 78 ☐ Corect
Producator : SGB ☐ Corect
Data fabricatiei : 01.10.2010 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari
Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 3

Sistem de detectie scurgeri : Rezervor 2 monocompartimentat ☐ Corect
Cod echipament : RO_013923 ☐ Corect
Serie echipament : 79 ☐ Corect
Producator : SGB ☐ Corect
Data fabricatiei : 01.10.2010 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari
Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 3

Sistem de detectie scurgeri : Rezervor 3 bicompartimentat ☐ Corect
Cod echipament : RO_013924 ☐ Corect
Serie echipament : 80 ☐ Corect
Producator : SGB ☐ Corect
Data fabricatiei : 01.10.2010 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari
Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____