

FISA VALIDARE INVENTAR

R1765 - MPP Oradea Episcopia



DATE GENERALE STATIE

Cod statie	:	R1765	Data verificarii	:	
Nume statie	:	MPP Oradea Episcopia	Persoana care verifica	:	
Numar distribuitoare	:	5			
Numar echipamente Sistem masura rezervoare	:			7	
Numar echipamente Rezervoare / sisteme asociate	:			21	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 5 - Pompa 1/2

Cod echipament	:	RO_000830	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D1650271	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantuium510/T10001	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2016	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	Apollo	☐ Corect	

DISTRIBUITOR 2 DIN 5 - Pompa 3/4

Cod echipament	:	RO_000831	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D1650270	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantuium510/T10001	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2016	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	Apollo	☐ Corect	

DISTRIBUITOR 3 DIN 5 - Pompa 5/6

Cod echipament	:	RO_000832	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D1650272	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantuium510/T10001	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	01.01.2016	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	Apollo	☐ Corect	

DISTRIBUITOR 4 DIN 5 - Pompa 7/8

Cod echipament	:	RO_000833	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D1651108	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantuium510/T10001	☐ Corect	
Tip echipament	:	HS 1-2	☐ Corect	
Numar dispenser	:	Pompa 7/8	☐ Corect	
Data fabricatiei	:	01.01.2016	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	80 l/min	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1765 - MPP Oradea Episcopia



Numar pistoale : 2 ☐ Corect
Calculator pompa : Apollo ☐ Corect

DISTRIBUITOR 5 DIN 5 - Pompa Adblue 11/12

Cod echipament : RO_240843 ☐ Corect
Serie echipament : 943034/2022 ☐ Corect
Producator : Gilbarco Veeder-Root_SK700-2/ADBLUE

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

☐ Corect

Tip echipament : MPD2/4 (Container Ad Blue - OMV) ☐ Corect
Numar dispenser : Pompa Adblue 11/12 ☐ Corect
Data fabricatiei : 24.12.2022 ☐ Corect
Numar produse : ☐ Corect
Debit : ☐ Corect
Numar pistoale : ☐ Corect
Calculator pompa : ☐ Corect

Observatii:

FISA VALIDARE INVENTAR

R1765 - MPP Oradea Episcopia



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_000835	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 350R_	☐ Corect	
Tip echipament	:	Veeder-Root 350R	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_000836	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_000837	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_000838	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R3	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_000839	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R4	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1765 - MPP Oradea Episcopia



VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_000840	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	unknown_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	01.10.2010	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_236131	☐ Corect
Serie echipament	:	969	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	19.12.2020	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1765 - MPP Oradea Episcopia



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 5

Rezervor	:	R1 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_000842	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown_	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	

REZERVOR 2 DIN 5

Rezervor	:	R2 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_000845	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown_	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	

REZERVOR 3 DIN 5

Rezervor	:	R3 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_000848	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown_	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	

REZERVOR 4 DIN 5

Rezervor	:	R4 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R4 Extra 99	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_000851	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown_	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.10.2010	☐ Corect	

REZERVOR 5 DIN 5

Rezervor	:	Container AdBlue	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:		☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_240844	☐ Corect	

FISA VALIDARE INVENTAR

R1765 - MPP Oradea Episcopia



Serie echipament	:	822130641/2022	☐ Corect
Producator	:	Storage Partners	☐ Corect
Data fabricatiei	:	24.12.2022	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:		☐ Corect

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 4

Sistem de detectie scurgeri	:	Rezervor 1 monocompartimentat	☐ Corect
Cod echipament	:	RO_000854	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB_	☐ Corect
Data fabricatiei	:	01.10.2010	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 4

Sistem de detectie scurgeri	:	Rezervor 2 monocompartimentat	☐ Corect
Cod echipament	:	RO_000855	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB_	☐ Corect
Data fabricatiei	:	01.10.2010	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 4

Sistem de detectie scurgeri	:	Rezervor 3 monocompartimentat	☐ Corect
Cod echipament	:	RO_000856	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB_	☐ Corect
Data fabricatiei	:	01.10.2010	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 4 DIN 4

Sistem de detectie scurgeri	:	Rezervor 4 monocompartimentat	☐ Corect
Cod echipament	:	RO_000857	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB_	☐ Corect
Data fabricatiei	:	01.10.2010	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____