

FISA VALIDARE INVENTAR

R1921 - CLUJ-MARASTI



DATE GENERALE STATIE

Cod statie	:	R1921	Data verificarii	:	
Nume statie	:	CLUJ-MARASTI	Persoana care verifica	:	
Numar distribuitoare	:	4			
Numar echipamente Sistem masura rezervoare	:			8	
Numar echipamente Rezervoare / sisteme asociate	:			24	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 4 - Pompa 1/2

Cod echipament	:	RO_232493	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	684614	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	GILBRACO	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	APOLLO	☐ Corect	

DISTRIBUITOR 2 DIN 4 - Pompa 3/4

Cod echipament	:	RO_232494	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	684618	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	GILBRACO	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	APOLLO	☐ Corect	

DISTRIBUITOR 3 DIN 4 - Pompa 5/6

Cod echipament	:	RO_232495	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	684629	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	GILBRACO	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	APOLLO	☐ Corect	

DISTRIBUITOR 4 DIN 4 - Pompa 7/8

Cod echipament	:	RO_232496	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	684615	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	GILBRACO	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4 DM	☐ Corect	
Numar dispenser	:	Pompa 7/8	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1921 - CLUJ-MARASTI



Numar pistoale	:	8	☐ Corect	_____
Calculator pompa	:	APOLLO	☐ Corect	_____

FISA VALIDARE INVENTAR

R1921 - CLUJ-MARASTI



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect
Cod echipament	:	RO_224835	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root 350R_	☐ Corect
Tip echipament	:	Veeder-Root 350R	☐ Corect
Data fabricatiei	:	31.07.2000	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 1 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_224836	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R1/1	☐ Corect
Data fabricatiei	:	31.07.2000	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 2 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_224837	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R1/2	☐ Corect
Data fabricatiei	:	31.07.2000	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 3 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_224838	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2	☐ Corect
Data fabricatiei	:	31.07.2000	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 4 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_224839	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3	☐ Corect
Data fabricatiei	:	31.07.2000	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1921 - CLUJ-MARASTI



SONDA NIVEL 5 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_224840	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R4	☐ Corect
Data fabricatiei	:	31.07.2000	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_224841	☐ Corect
Serie echipament	:	36	☐ Corect
Prodicator	:	TEHNOMETAL	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	01.01.1997	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_224842	☐ Corect
Serie echipament	:	128	☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 4m	☐ Corect
Data fabricatiei	:	05.06.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1921 - CLUJ-MARASTI



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 5

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_224843	☐ Corect	
Serie echipament	:	52A	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2000	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	31.07.2000	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	31.07.2000	☐ Corect	

REZERVOR 2 DIN 5

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_224846	☐ Corect	
Serie echipament	:	52B	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2000	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	31.07.2000	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	31.07.2000	☐ Corect	

REZERVOR 3 DIN 5

Rezervor	:	R2 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2 MM 100+	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_224849	☐ Corect	
Serie echipament	:	47	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2000	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	31.07.2000	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	31.07.2000	☐ Corect	

REZERVOR 4 DIN 5

Rezervor	:	R3 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3 MM 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_224852	☐ Corect	
Serie echipament	:	43	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2000	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	31.07.2000	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	31.07.2000	☐ Corect	

REZERVOR 5 DIN 5

Rezervor	:	R4 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R4 OMV Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_224855	☐ Corect	

FISA VALIDARE INVENTAR

R1921 - CLUJ-MARASTI



Serie echipament	:	40	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.01.2000	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	31.07.2000	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	31.07.2000	☐ Corect

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 4

Sistem de detectie scurgeri	:	Rezervor 1 bicompartimentat	☐ Corect
Cod echipament	:	RO_224858	☐ Corect
Serie echipament	:	228304	☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	01.01.2000	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 4

Sistem de detectie scurgeri	:	Rezervor 2 monocompartimentat	☐ Corect
Cod echipament	:	RO_224859	☐ Corect
Serie echipament	:	228290	☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	01.01.2000	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 4

Sistem de detectie scurgeri	:	Rezervor 3 monocompartimentat	☐ Corect
Cod echipament	:	RO_224860	☐ Corect
Serie echipament	:	228295	☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	01.01.2000	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 4 DIN 4

Sistem de detectie scurgeri	:	Rezervor 4 monocompartimentat	☐ Corect
Cod echipament	:	RO_224861	☐ Corect
Serie echipament	:	229204	☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	01.01.2000	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____