

FISA VALIDARE INVENTAR

R1922 - CLUJ-TURZII



DATE GENERALE STATIE

Cod statie	:	R1922	Data verificarii	:	
Nume statie	:	CLUJ-TURZII	Persoana care verifica	:	
Numar distribuitoare	:	4			
Numar echipamente Sistem masura rezervoare	:			8	
Numar echipamente Rezervoare / sisteme asociate	:			24	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 4 - Pompa 1/2

Cod echipament	:	RO_225966	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	677625	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	GILBARCO	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	APOLLO	☐ Corect	

DISTRIBUITOR 2 DIN 4 - Pompa 3/4

Cod echipament	:	RO_225967	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	677624	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	GILBARCO	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	APOLLO	☐ Corect	

DISTRIBUITOR 3 DIN 4 - Pompa 5/6

Cod echipament	:	RO_225968	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	677622	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	GILBARCO	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	APOLLO	☐ Corect	

DISTRIBUITOR 4 DIN 4 - Pompa 7/8

Cod echipament	:	RO_225969	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	677623	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	GILBARCO	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 7/8	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1922 - CLUJ-TURZII



Numar pistoale	:	8	☐ Corect	_____
Calculator pompa	:	APOLLO	☐ Corect	_____

FISA VALIDARE INVENTAR

R1922 - CLUJ-TURZII



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect
Cod echipament	:	RO_225971	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root 350R_	☐ Corect
Tip echipament	:	Veeder-Root 350R	☐ Corect
Data fabricatiei	:	21.12.1999	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 1 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_225972	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R1/1	☐ Corect
Data fabricatiei	:	21.12.1999	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 2 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_225973	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R1/2	☐ Corect
Data fabricatiei	:	21.12.1999	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 3 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_225974	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2	☐ Corect
Data fabricatiei	:	21.12.1999	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 4 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_225975	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3	☐ Corect
Data fabricatiei	:	21.12.1999	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1922 - CLUJ-TURZII



SONDA NIVEL 5 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_225976	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R4	☐ Corect
Data fabricatiei	:	21.12.1999	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_225977	☐ Corect
Serie echipament	:	FS	☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	01.01.1999	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_236138	☐ Corect
Serie echipament	:	976	☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	19.12.2020	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1922 - CLUJ-TURZII



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 5

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 MM 100+	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_225979	☐ Corect	
Serie echipament	:	11A	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.1999	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	21.12.1999	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	21.12.1999	☐ Corect	

REZERVOR 2 DIN 5

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 MM 100+	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_225982	☐ Corect	
Serie echipament	:	11B	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.1999	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	21.12.1999	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	21.12.1999	☐ Corect	

REZERVOR 3 DIN 5

Rezervor	:	R2 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_225985	☐ Corect	
Serie echipament	:	18	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.1999	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	21.12.1999	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	21.12.1999	☐ Corect	

REZERVOR 4 DIN 5

Rezervor	:	R3 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3 MM 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_225988	☐ Corect	
Serie echipament	:	19	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.1999	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	21.12.1999	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	21.12.1999	☐ Corect	

REZERVOR 5 DIN 5

Rezervor	:	R4 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R4 OMV Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_225991	☐ Corect	

FISA VALIDARE INVENTAR

R1922 - CLUJ-TURZII



Serie echipament	:	8	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.01.1999	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	21.12.1999	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	21.12.1999	☐ Corect

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 4

Sistem de detectie scurgeri	:	Rezervor 1 bicompartimentat	☐ Corect
Cod echipament	:	RO_225994	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	21.12.1999	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 4

Sistem de detectie scurgeri	:	Rezervor 2 monocompartimentat	☐ Corect
Cod echipament	:	RO_225995	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	21.12.1999	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 4

Sistem de detectie scurgeri	:	Rezervor 3 monocompartimentat	☐ Corect
Cod echipament	:	RO_225996	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	21.12.1999	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 4 DIN 4

Sistem de detectie scurgeri	:	Rezervor 4 monocompartimentat	☐ Corect
Cod echipament	:	RO_225997	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	21.12.1999	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____