

FISA VALIDARE INVENTAR

R1923 - CLUJ-VUIA



DATE GENERALE STATIE

Cod statie	:	R1923	Data verificarii	:	
Nume statie	:	CLUJ-VUIA	Persoana care verifica	:	
Numar distribuitoare	:	3			
Numar echipamente Sistem masura rezervoare	:			8	
Numar echipamente Rezervoare / sisteme asociate	:			23	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 3 - Pompa 1/2

Cod echipament	:	RO_225186	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	677591	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	GILBARCO	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	APOLLO	☐ Corect	

DISTRIBUITOR 2 DIN 3 - Pompa 3/4

Cod echipament	:	RO_225187	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	677590	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	GILBARCO	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	APOLLO	☐ Corect	

DISTRIBUITOR 3 DIN 3 - Pompa 5/6

Cod echipament	:	RO_225188	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	677589	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	GILBARCO	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	APOLLO	☐ Corect	

FISA VALIDARE INVENTAR

R1923 - CLUJ-VUIA



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect
Cod echipament	:	RO_225190	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root 350R_	☐ Corect
Tip echipament	:	Veeder-Root 350R	☐ Corect
Data fabricatiei	:	12.10.2004	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 1 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_225191	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R1/1	☐ Corect
Data fabricatiei	:	12.10.2004	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 2 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_225192	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R1/2	☐ Corect
Data fabricatiei	:	12.10.2004	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 3 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_225193	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2/1	☐ Corect
Data fabricatiei	:	12.10.2004	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SONDA NIVEL 4 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_225194	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2/2	☐ Corect
Data fabricatiei	:	12.10.2004	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1923 - CLUJ-VUIA



SONDA NIVEL 5 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_225195	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R3	☐ Corect
Data fabricatiei	:	12.10.2004	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_225196	☐ Corect
Serie echipament	:	FS	☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	12.10.2004	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_225197	☐ Corect
Serie echipament	:	129	☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 4m	☐ Corect
Data fabricatiei	:	05.06.2019	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1923 - CLUJ-VUIA



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 5

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_225198	☐ Corect	
Serie echipament	:	326A	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2004	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	12.10.2004	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	12.10.2004	☐ Corect	

REZERVOR 2 DIN 5

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_225201	☐ Corect	
Serie echipament	:	326B	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2004	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	12.10.2004	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	12.10.2004	☐ Corect	

REZERVOR 3 DIN 5

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_225204	☐ Corect	
Serie echipament	:	207A	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2004	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	12.10.2004	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	12.10.2004	☐ Corect	

REZERVOR 4 DIN 5

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Extra 99	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_225207	☐ Corect	
Serie echipament	:	207B	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2004	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	12.10.2004	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	12.10.2004	☐ Corect	

REZERVOR 5 DIN 5

Rezervor	:	R3 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_225210	☐ Corect	

FISA VALIDARE INVENTAR

R1923 - CLUJ-VUIA



Serie echipament	:	328	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.01.2004	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	12.10.2004	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	12.10.2004	☐ Corect

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 3

Sistem de detectie scurgeri	:	Rezervor 1 bicompartimentat	☐ Corect
Cod echipament	:	RO_225213	☐ Corect
Serie echipament	:	259976	☐ Corect
Producator	:	LECKANZEIGER	☐ Corect
Data fabricatiei	:	01.01.2004	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 3

Sistem de detectie scurgeri	:	Rezervor 2 bicompartimentat	☐ Corect
Cod echipament	:	RO_225214	☐ Corect
Serie echipament	:	259975	☐ Corect
Producator	:	LECKANZEIGER	☐ Corect
Data fabricatiei	:	01.01.2004	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 3

Sistem de detectie scurgeri	:	Rezervor 3 monocompartimentat	☐ Corect
Cod echipament	:	RO_225215	☐ Corect
Serie echipament	:	406609	☐ Corect
Producator	:	LECKANZEIGER	☐ Corect
Data fabricatiei	:	01.01.2018	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____