

FISA VALIDARE INVENTAR

R1936 - 51 Oradea



DATE GENERALE STATIE

Cod statie	: R1936	Data verificarii	:
Nume statie	: 51 Oradea	Persoana care verifica	:
Numar distribuitoare	: 6		
Numar echipamente Sistem masura rezervoare	:	10	
Numar echipamente Rezervoare / sisteme asociate	:	34	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 6 - Pompa 4/3

Cod echipament	: RO_001190	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 679423	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	: HS 1-2	☐ Corect	
Numar dispenser	: Pompa 4/3	☐ Corect	
Data fabricatiei	: 01.01.2018	☐ Corect	
Numar produse	: 1	☐ Corect	
Debit	: 80 l/min	☐ Corect	Observatii:
Numar pistoale	: 2	☐ Corect	
Calculator pompa	: Apollo	☐ Corect	

DISTRIBUITOR 2 DIN 6 - Pompa1/2

Cod echipament	: RO_001191	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 679424	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	: HS 1-2	☐ Corect	
Numar dispenser	: Pompa1/2	☐ Corect	
Data fabricatiei	: 01.01.2018	☐ Corect	
Numar produse	: 1	☐ Corect	
Debit	: 80 l/min	☐ Corect	Observatii:
Numar pistoale	: 2	☐ Corect	
Calculator pompa	: Apollo	☐ Corect	

DISTRIBUITOR 3 DIN 6 - Pompa 9/10

Cod echipament	: RO_001192	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 679422	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 9/10	☐ Corect	
Data fabricatiei	: 01.01.2018	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: Apollo	☐ Corect	

DISTRIBUITOR 4 DIN 6 - Pompa 7/8

Cod echipament	: RO_001193	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 679421	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 7/8	☐ Corect	
Data fabricatiei	: 01.01.2018	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1936 - 51 Oradea



Numar pistoale : 8 ☐ Corect
Calculator pompa : Apollo ☐ Corect

DISTRIBUITOR 5 DIN 6 - Pompa 5/6

Cod echipament : RO_001194 ☐ Corect
Serie echipament : 679420 ☐ Corect
Producator : Gilbarco Veeder-Root_SK700-2 ☐ Corect
Tip echipament : MPD 4/8 VR 2/4 ☐ Corect
Numar dispenser : Pompa 5/6 ☐ Corect
Data fabricatiei : 01.01.2018 ☐ Corect
Numar produse : 4 ☐ Corect
Debit : 40 l/min ☐ Corect
Numar pistoale : 8 ☐ Corect
Calculator pompa : Apollo ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DISTRIBUITOR 6 DIN 6 - Adblue

Cod echipament : RO_001195 ☐ Corect
Serie echipament : 679425 ☐ Corect
Producator : Gilbarco Veeder-Root_SK700-2/ADBLUE ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

☐ Corect

Tip echipament : MPD 1/2 (Ad Blue - OMV) ☐ Corect
Numar dispenser : Adblue ☐ Corect
Data fabricatiei : 01.01.2018 ☐ Corect
Numar produse : 1 ☐ Corect
Debit : 80 l/min ☐ Corect
Numar pistoale : 2 ☐ Corect
Calculator pompa : Apollo ☐ Corect

Observatii:

FISA VALIDARE INVENTAR

R1936 - 51 Oradea



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_001197	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 350R_	☐ Corect	
Tip echipament	:	Veeder-Root 350R	☐ Corect	
Data fabricatiei	:	10.11.2001	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 7

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_001198	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1	☐ Corect	
Data fabricatiei	:	10.11.2001	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 7

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_001199	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1	☐ Corect	
Data fabricatiei	:	10.11.2001	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 7

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_001200	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/2	☐ Corect	
Data fabricatiei	:	10.11.2001	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 7

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_001201	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R3	☐ Corect	
Data fabricatiei	:	10.11.2001	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1936 - 51 Oradea



SONDA NIVEL 5 DIN 7

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_001202	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R4	☐ Corect	_____
Data fabricatiei	:	10.11.2001	☐ Corect	Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_001203	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	unknown_	☐ Corect	_____
Tip echipament	:	Vas etalon	☐ Corect	_____
Data fabricatiei	:	31.07.2010	☐ Corect	Observatii:

SONDA NIVEL 6 DIN 7

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_001352	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R5	☐ Corect	_____
Data fabricatiei	:	10.11.2001	☐ Corect	Observatii:

SONDA NIVEL 7 DIN 7

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_001353	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R6	☐ Corect	_____
Data fabricatiei	:	10.11.2001	☐ Corect	Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_236139	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	968	☐ Corect	_____
Producator	:	Mecaf_	☐ Corect	_____
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect	_____
Data fabricatiei	:	19.12.2020	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1936 - 51 Oradea



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 7

Rezervor	:	R6 monocompartmentat Adblue	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R6 Adblue	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_001205	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown_	☐ Corect	
Data fabricatiei	:	10.11.2001	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	10.11.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	10.11.2001	☐ Corect	

REZERVOR 2 DIN 7

Rezervor	:	R1 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1 OMV Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_001208	☐ Corect	
Serie echipament	:	367	☐ Corect	
Producator	:	unknown_	☐ Corect	
Data fabricatiei	:	01.01.2001	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.01.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	10.11.2001	☐ Corect	

REZERVOR 3 DIN 7

Rezervor	:	R2/1 bicompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_001211	☐ Corect	
Serie echipament	:	368/1	☐ Corect	
Producator	:	unknown_	☐ Corect	
Data fabricatiei	:	01.01.2001	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.01.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	10.11.2001	☐ Corect	

REZERVOR 4 DIN 7

Rezervor	:	R2/2 bicompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_001214	☐ Corect	
Serie echipament	:	368/2	☐ Corect	
Producator	:	unknown_	☐ Corect	
Data fabricatiei	:	01.01.2001	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.01.2001	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	10.11.2001	☐ Corect	

REZERVOR 5 DIN 7

Rezervor	:	R3 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3 MM95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_001217	☐ Corect	

FISA VALIDARE INVENTAR

R1936 - 51 Oradea



Serie echipament	:	369	☐ Corect
Producator	:	unknown_	☐ Corect
Data fabricatiei	:	01.01.2001	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	01.01.2001	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	10.11.2001	☐ Corect

Observatii:

REZERVOR 6 DIN 7

Rezervor	:	R4 monocompartimentat	☐ Corect
Produs	:	R4 MM100+	☐ Corect
Cod echipament	:	RO_001220	☐ Corect
Serie echipament	:	370	☐ Corect
Producator	:	unknown_	☐ Corect
Data fabricatiei	:	01.01.2001	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	01.01.2001	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	10.11.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

REZERVOR 7 DIN 7

Rezervor	:	R5 monocompartimentat	☐ Corect
Produs	:	R5 OMV Diesel	☐ Corect
Cod echipament	:	RO_001223	☐ Corect
Serie echipament	:	FS	☐ Corect
Producator	:	unknown_	☐ Corect
Data fabricatiei	:	10.11.2001	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	01.01.2001	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	10.11.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 6

Sistem de detectie scurgeri	:	Rezervor 1 monocompartimentat	☐ Corect
Cod echipament	:	RO_001226	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB_	☐ Corect
Data fabricatiei	:	10.11.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 6

Sistem de detectie scurgeri	:	Rezervor 2 bicompartimentat	☐ Corect
Cod echipament	:	RO_001227	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB_	☐ Corect
Data fabricatiei	:	10.11.2001	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 6

Sistem de detectie scurgeri	:	Rezervor 3 monocompartimentat	☐ Corect
Cod echipament	:	RO_001228	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB_	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

FISA VALIDARE INVENTAR

R1936 - 51 Oradea



Data fabricatiei : 10.11.2001

☐ Corect

Observatii:

SISTEM DE DETECTIE SCURGERI 4 DIN 6

Sistem de detectie scurgeri : Rezervor 4 monocompartimentat ☐ Corect
Cod echipament : RO_001229 ☐ Corect
Serie echipament : ☐ Corect
Producator : SGB_ ☐ Corect
Data fabricatiei : 10.11.2001 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 5 DIN 6

Sistem de detectie scurgeri : Rezervor 5 monocompartimentat ☐ Corect
Cod echipament : RO_001230 ☐ Corect
Serie echipament : ☐ Corect
Producator : SGB_ ☐ Corect
Data fabricatiei : 10.11.2001 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 6 DIN 6

Sistem de detectie scurgeri : Rezervor 6 monocompartimentat ☐ Corect
Cod echipament : RO_001231 ☐ Corect
Serie echipament : ☐ Corect
Producator : SGB_ ☐ Corect
Data fabricatiei : 10.11.2001 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____