

FISA VALIDARE INVENTAR

R1937 - 52 Oradea



DATE GENERALE STATIE

Cod statie	: R1937	Data verificarii	:
Nume statie	: 52 Oradea	Persoana care verifica	:
Numar distribuitoare	: 3		
Numar echipamente Sistem masura rezervoare	:	8	
Numar echipamente Rezervoare / sisteme asociate	:	24	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 3 - Pompa 1/2

Cod echipament	: RO_238888	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 943295	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco SK700	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 1/2	☐ Corect	
Data fabricatiei	: 01.10.2022	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: Apollo	☐ Corect	

DISTRIBUITOR 2 DIN 3 - Pompa 3/4

Cod echipament	: RO_238889	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 943296	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco SK700	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 3/4	☐ Corect	
Data fabricatiei	: 01.10.2022	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: Apollo	☐ Corect	

DISTRIBUITOR 3 DIN 3 - Pompa 5/6

Cod echipament	: RO_238890	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: 943297	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Gilbarco SK700	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 5/6	☐ Corect	
Data fabricatiei	: 01.10.2022	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: Apollo	☐ Corect	

FISA VALIDARE INVENTAR

R1937 - 52 Oradea



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_001364	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 350R_	☐ Corect	
Tip echipament	:	Veeder-Root 350R	☐ Corect	
Data fabricatiei	:	17.08.2002	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_001365	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1	☐ Corect	
Data fabricatiei	:	17.08.2002	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_001366	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1	☐ Corect	
Data fabricatiei	:	17.08.2002	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_001367	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/2	☐ Corect	
Data fabricatiei	:	17.08.2002	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_001368	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R3	☐ Corect	
Data fabricatiei	:	17.08.2002	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1937 - 52 Oradea



SONDA NIVEL 5 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_001369	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R4	☐ Corect
Data fabricatiei	:	17.08.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_001370	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	unknown_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	17.08.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_235663	☐ Corect
Serie echipament	:	549	☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	12.06.2020	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1937 - 52 Oradea



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 5

Rezervor	:	R1 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1 MM95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_001372	☐ Corect	
Serie echipament	:	415	☐ Corect	
Producator	:	unknown_	☐ Corect	
Data fabricatiei	:	17.08.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	17.08.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	17.08.2002	☐ Corect	

REZERVOR 2 DIN 5

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_001375	☐ Corect	
Serie echipament	:	416/1	☐ Corect	
Producator	:	unknown_	☐ Corect	
Data fabricatiei	:	17.08.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	17.08.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	17.08.2002	☐ Corect	

REZERVOR 3 DIN 5

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_001378	☐ Corect	
Serie echipament	:	416/2	☐ Corect	
Producator	:	unknown_	☐ Corect	
Data fabricatiei	:	17.08.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	17.08.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	17.08.2002	☐ Corect	

REZERVOR 4 DIN 5

Rezervor	:	R3 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3 MM100+	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_001381	☐ Corect	
Serie echipament	:	417	☐ Corect	
Producator	:	unknown_	☐ Corect	
Data fabricatiei	:	17.08.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	17.08.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	17.08.2002	☐ Corect	

REZERVOR 5 DIN 5

Rezervor	:	R4 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R4 OMV Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_001384	☐ Corect	

FISA VALIDARE INVENTAR

R1937 - 52 Oradea



Serie echipament	:	418	☐ Corect
Producator	:	unknown_	☐ Corect
Data fabricatiei	:	17.08.2002	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	17.08.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	17.08.2002	☐ Corect

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 4

Sistem de detectie scurgeri	:	Rezervor 1 monocompartimentat	☐ Corect
Cod echipament	:	RO_001387	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB_	☐ Corect
Data fabricatiei	:	17.08.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 4

Sistem de detectie scurgeri	:	Rezervor 2 bicompartimentat	☐ Corect
Cod echipament	:	RO_001388	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB_	☐ Corect
Data fabricatiei	:	17.08.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 4

Sistem de detectie scurgeri	:	Rezervor 3 monocompartimentat	☐ Corect
Cod echipament	:	RO_001389	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB_	☐ Corect
Data fabricatiei	:	17.08.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 4 DIN 4

Sistem de detectie scurgeri	:	Rezervor 4 monocompartimentat	☐ Corect
Cod echipament	:	RO_001390	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB_	☐ Corect
Data fabricatiei	:	17.08.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____