

FISA VALIDARE INVENTAR

R1952 - SIMERIA



DATE GENERALE STATIE

Cod statie	:	R1952	Data verificarii	:	
Nume statie	:	SIMERIA	Persoana care verifica	:	
Numar distribuitoare	:	3			
Numar echipamente Sistem masura rezervoare	:			8	
Numar echipamente Rezervoare / sisteme asociate	:			24	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 3 - Pompa 5/6

Cod echipament	:	RO_017171	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D1141110	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	TOKHEIM_Quantum 510	☐ Corect	
Tip echipament	:	HS 1-2	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	01.01.2011	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	130 l/min	☐ Corect	Observatii:
Numar pistoale	:	2	☐ Corect	
Calculator pompa	:	WWC	☐ Corect	

DISTRIBUITOR 2 DIN 3 - Pompa 1/2

Cod echipament	:	RO_017172	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	280420	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Nouvo Pignone_DPX	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2003	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	WWC	☐ Corect	

DISTRIBUITOR 3 DIN 3 - Pompa 3/4

Cod echipament	:	RO_017173	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	280419	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Nouvo Pignone_DPX	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2003	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	WWC	☐ Corect	

FISA VALIDARE INVENTAR

R1952 - SIMERIA



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_017175	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	D02130192208002	☐ Corect	_____
Producator	:	Veeder-Root 350R_	☐ Corect	_____
Tip echipament	:	Veeder-Root 350R_	☐ Corect	_____
Data fabricatiei	:	01.08.2003	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_017175	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R1	☐ Corect	_____
Data fabricatiei	:	01.08.2003	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_017177	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R2	☐ Corect	_____
Data fabricatiei	:	01.08.2003	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_017178	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R3/1	☐ Corect	_____
Data fabricatiei	:	01.08.2003	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_017179	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R3/2	☐ Corect	_____
Data fabricatiei	:	01.08.2003	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1952 - SIMERIA



SONDA NIVEL 5 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_017180	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R4	☐ Corect
Data fabricatiei	:	01.08.2003	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_017181	☐ Corect
Serie echipament	:	65/2003	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	01.08.2003	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_017182	☐ Corect
Serie echipament	:	524	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	30.04.2009	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1952 - SIMERIA



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 5

Rezervor	:	R1 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1 MM 100+	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_017183	☐ Corect	
Serie echipament	:	242	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.08.2003	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.08.2003	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.08.2003	☐ Corect	

REZERVOR 2 DIN 5

Rezervor	:	R2 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2 MM 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_017186	☐ Corect	
Serie echipament	:	240	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.08.2003	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.08.2003	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.08.2003	☐ Corect	

REZERVOR 3 DIN 5

Rezervor	:	R3/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3/1 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_017189	☐ Corect	
Serie echipament	:	239	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.08.2003	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.08.2003	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.08.2003	☐ Corect	

REZERVOR 4 DIN 5

Rezervor	:	R3/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3/2 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_017192	☐ Corect	
Serie echipament	:	239	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.08.2003	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	01.08.2003	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	01.08.2003	☐ Corect	

REZERVOR 5 DIN 5

Rezervor	:	R4 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R4 OMV Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_017195	☐ Corect	

FISA VALIDARE INVENTAR

R1952 - SIMERIA



Serie echipament	:	241	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.08.2003	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	01.08.2003	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	01.08.2003	☐ Corect

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 4

Sistem de detectie scurgeri	:	Rezervor 1 monocompartimentat	☐ Corect
Cod echipament	:	RO_017198	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	01.08.2003	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 4

Sistem de detectie scurgeri	:	Rezervor 2 monocompartimentat	☐ Corect
Cod echipament	:	RO_017199	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	01.08.2003	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 4

Sistem de detectie scurgeri	:	Rezervor 3 bicompartimentat	☐ Corect
Cod echipament	:	RO_017200	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	01.08.2003	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 4 DIN 4

Sistem de detectie scurgeri	:	Rezervor 4 monocompartimentat	☐ Corect
Cod echipament	:	RO_017201	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	01.08.2003	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____