

FISA VALIDARE INVENTAR

R1958 - TIMISOARA 1



DATE GENERALE STATIE

Cod statie	:	R1958	Data verificarii	:	
Nume statie	:	TIMISOARA 1	Persoana care verifica	:	
Numar distribuitoare	:	4			
Numar echipamente Sistem masura rezervoare	:			8	
Numar echipamente Rezervoare / sisteme asociate	:			23	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 4 - Pompa 1/2

Cod echipament	:	RO_011162	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	679447	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	SK700	☐ Corect	

DISTRIBUITOR 2 DIN 4 - Pompa 3/4

Cod echipament	:	RO_011163	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	679448	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	SK700	☐ Corect	

DISTRIBUITOR 3 DIN 4 - Pompa 7/8

Cod echipament	:	RO_011164	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	679449	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 7/8	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	SK700	☐ Corect	

DISTRIBUITOR 4 DIN 4 - Pompa 5/6

Cod echipament	:	RO_011165	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	679450	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco Veeder-Root_SK700-2	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1958 - TIMISOARA 1



Numar pistoale	:	8	☐ Corect	_____
Calculator pompa	:	SK700	☐ Corect	_____

FISA VALIDARE INVENTAR

R1958 - TIMISOARA 1



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_011167	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	A0773169323012	☐ Corect	_____
Producator	:	Veeder-Root 350R_	☐ Corect	_____
Tip echipament	:	Veeder-Root 350R	☐ Corect	_____
Data fabricatiei	:	23.09.2000	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_011168	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R1	☐ Corect	_____
Data fabricatiei	:	23.09.2000	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_011169	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R2	☐ Corect	_____
Data fabricatiei	:	23.09.2000	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_011170	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R3	☐ Corect	_____
Data fabricatiei	:	23.09.2000	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_011171	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	_____
Producator	:	Veeder-Root_	☐ Corect	_____
Tip echipament	:	Sonda R4/1	☐ Corect	_____
Data fabricatiei	:	23.09.2000	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1958 - TIMISOARA 1



SONDA NIVEL 5 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_011172	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R4/2	☐ Corect
Data fabricatiei	:	23.09.2000	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_011173	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	23.09.2000	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_011174	☐ Corect
Serie echipament	:	717	☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	31.05.2009	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1958 - TIMISOARA 1



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 5

Rezervor	:	R1 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1 OMV Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_011175	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	23.09.2000	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	23.09.2000	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	23.09.2000	☐ Corect	

REZERVOR 2 DIN 5

Rezervor	:	R2 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2 MM 100+	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_011178	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	23.09.2000	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	23.09.2000	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	23.09.2000	☐ Corect	

REZERVOR 3 DIN 5

Rezervor	:	R3 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3 MM 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_011181	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	23.09.2000	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	23.09.2000	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	23.09.2000	☐ Corect	

REZERVOR 4 DIN 5

Rezervor	:	R4/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R4/1 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_011184	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	23.09.2000	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	23.09.2000	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	23.09.2000	☐ Corect	

REZERVOR 5 DIN 5

Rezervor	:	R4/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R4/2 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_011187	☐ Corect	

FISA VALIDARE INVENTAR

R1958 - TIMISOARA 1



Serie echipament	:		☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	23.09.2000	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	23.09.2000	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	23.09.2000	☐ Corect

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 3

Sistem de detectie scurgeri	:	Rezervor 1 monocompartimentat	☐ Corect
Cod echipament	:	RO_011190	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	14.08.2023	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 3

Sistem de detectie scurgeri	:	Rezervor 2 monocompartimentat	☐ Corect
Cod echipament	:	RO_011191	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	14.08.2023	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 3

Sistem de detectie scurgeri	:	Rezervor 3 bicompartimentat	☐ Corect
Cod echipament	:	RO_011192	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	14.08.2023	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____