

FISA VALIDARE INVENTAR

R1962 - TIMISOARA 5



DATE GENERALE STATIE

Cod statie	:	R1962	Data verificarii	:	
Nume statie	:	TIMISOARA 5	Persoana care verifica	:	
Numar distribuitoare	:	2			
Numar echipamente Sistem masura rezervoare	:			8	
Numar echipamente Rezervoare / sisteme asociate	:			22	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 2 - Pompa 1/2

Cod echipament	:	RO_011682	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	289315	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Nuovo Pignone DPX-F	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	Nuovo Pignone (CL)	☐ Corect	

DISTRIBUITOR 2 DIN 2 - Pompa 3/4

Cod echipament	:	RO_011683	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	286917	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Nuovo Pignone DPX-F	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	Nuovo Pignone (CL)	☐ Corect	

FISA VALIDARE INVENTAR

R1962 - TIMISOARA 5



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_011685	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 350R_	☐ Corect	
Tip echipament	:	Veeder-Root 350R	☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_011686	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/1	☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_011687	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/2	☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_011688	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/3	☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_011689	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1	☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1962 - TIMISOARA 5



SONDA NIVEL 5 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_011690	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Veeder-Root_	☐ Corect
Tip echipament	:	Sonda R2/2	☐ Corect
Data fabricatiei	:	09.09.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_011691	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	09.09.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_011692	☐ Corect
Serie echipament	:	800	☐ Corect
Prodicator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	31.05.2009	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1962 - TIMISOARA 5



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 5

Rezervor	:	R1/1 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 MM 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_011693	☐ Corect	
Serie echipament	:	465	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	

REZERVOR 2 DIN 5

Rezervor	:	R1/2 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 MM 100+	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_011696	☐ Corect	
Serie echipament	:	465	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	

REZERVOR 3 DIN 5

Rezervor	:	R1/3 tricompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/3 MM 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_011699	☐ Corect	
Serie echipament	:	465	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	

REZERVOR 4 DIN 5

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 OMV Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_011702	☐ Corect	
Serie echipament	:	463	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	09.09.2002	☐ Corect	

REZERVOR 5 DIN 5

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_011705	☐ Corect	

FISA VALIDARE INVENTAR

R1962 - TIMISOARA 5



Serie echipament	:	463	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	09.09.2002	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	09.09.2002	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	09.09.2002	☐ Corect

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 2

Sistem de detectie scurgeri	:	Rezervor 1 tricompartimentat	☐ Corect
Cod echipament	:	RO_011708	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	09.09.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 2

Sistem de detectie scurgeri	:	Rezervor 2 bicompartimentat	☐ Corect
Cod echipament	:	RO_011709	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	SGB	☐ Corect
Data fabricatiei	:	09.09.2002	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____