

FISA VALIDARE INVENTAR

R1969 - Cluj Ring Road



DATE GENERALE STATIE

Cod statie	: R1969	Data verificarii	:
Nume statie	: Cluj Ring Road	Persoana care verifica	:
Numar distribuitoare	: 5		
Numar echipamente Sistem masura rezervoare	:	8	
Numar echipamente Rezervoare / sisteme asociate	:	26	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 5 - Pompa 1/2

Cod echipament	: RO_225608	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: D1322142	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Tokheim_Quantium 510	☐ Corect	
Tip echipament	: HS 1-2	☐ Corect	
Numar dispenser	: Pompa 1/2	☐ Corect	
Data fabricatiei	: 01.01.2013	☐ Corect	
Numar produse	: 1	☐ Corect	
Debit	: 130 l/min	☐ Corect	Observatii:
Numar pistoale	: 2	☐ Corect	
Calculator pompa	: TQC	☐ Corect	

DISTRIBUITOR 2 DIN 5 - Pompa 3/4

Cod echipament	: RO_225609	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: D1322145	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Tokheim_Quantium 510	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 3/4	☐ Corect	
Data fabricatiei	: 01.01.2013	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: TQC	☐ Corect	

DISTRIBUITOR 3 DIN 5 - Pompa 5/6

Cod echipament	: RO_225610	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: D1322143	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Tokheim_Quantium 510	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 5/6	☐ Corect	
Data fabricatiei	: 01.01.2013	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:
Numar pistoale	: 8	☐ Corect	
Calculator pompa	: TQC	☐ Corect	

DISTRIBUITOR 4 DIN 5 - Pompa 7/8

Cod echipament	: RO_225611	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	: D1322144	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	: Tokheim_Quantium 510	☐ Corect	
Tip echipament	: MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	: Pompa 7/8	☐ Corect	
Data fabricatiei	: 01.01.2013	☐ Corect	
Numar produse	: 4	☐ Corect	
Debit	: 40 l/min	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1969 - Cluj Ring Road



Numar pistoale	:	8	☐ Corect	_____
Calculator pompa	:	TQC	☐ Corect	_____

DISTRIBUITOR 5 DIN 5 - Pompa 9/10

Cod echipament	:	RO_225612	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D1749287	☐ Corect	Valori corectate / informatii de pe placuta:
Prodicator	:	Tokheim_Quantium 510	☐ Corect	_____
Tip echipament	:	MPD 1/2 (Ad Blue - OMV)	☐ Corect	_____
Numar dispenser	:	Pompa 9/10	☐ Corect	_____
Data fabricatiei	:	01.01.2013	☐ Corect	_____
Numar produse	:	1	☐ Corect	_____
Debit	:		☐ Corect	Observatii:
Numar pistoale	:	2	☐ Corect	_____
Calculator pompa	:	TQC	☐ Corect	_____

FISA VALIDARE INVENTAR

R1969 - Cluj Ring Road



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_225614	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 450R	☐ Corect	
Tip echipament	:	Veeder-Root 450R	☐ Corect	
Data fabricatiei	:	12.08.2013	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_225615	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1	☐ Corect	
Data fabricatiei	:	12.08.2013	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_225616	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1	☐ Corect	
Data fabricatiei	:	12.08.2013	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_225617	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/2	☐ Corect	
Data fabricatiei	:	12.08.2013	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 5

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_225618	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R3/1	☐ Corect	
Data fabricatiei	:	12.08.2013	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1969 - Cluj Ring Road



SONDA NIVEL 5 DIN 5

Echipament	:	Sonda nivel	☐ Corect
Cod echipament	:	RO_225619	☐ Corect
Serie echipament	:		☐ Corect
Prodicator	:	Veeder-Root	☐ Corect
Tip echipament	:	Sonda R3/2	☐ Corect
Data fabricatiei	:	12.08.2013	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_225620	☐ Corect
Serie echipament	:	37	☐ Corect
Prodicator	:	DELTA IMPEX	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	01.01.2012	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_236142	☐ Corect
Serie echipament	:	953	☐ Corect
Prodicator	:	Mecaf	☐ Corect
Tip echipament	:	Rigla metalica Rigla 4m	☐ Corect
Data fabricatiei	:	19.12.2020	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1969 - Cluj Ring Road



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 6

Rezervor	:	R1 monocompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1 OMV Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_225622	☐ Corect	
Serie echipament	:	4	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2013	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	12.08.2013	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	12.08.2013	☐ Corect	

REZERVOR 2 DIN 6

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 MM 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_225625	☐ Corect	
Serie echipament	:	6	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2013	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	12.08.2013	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	12.08.2013	☐ Corect	

REZERVOR 3 DIN 6

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 MM 100+	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_225628	☐ Corect	
Serie echipament	:	6	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2013	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	12.08.2013	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	12.08.2013	☐ Corect	

REZERVOR 4 DIN 6

Rezervor	:	R3/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3/1 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_225631	☐ Corect	
Serie echipament	:	5	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2013	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	12.08.2013	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	12.08.2013	☐ Corect	

REZERVOR 5 DIN 6

Rezervor	:	R3/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R3/2 OMV Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_225634	☐ Corect	

FISA VALIDARE INVENTAR

R1969 - Cluj Ring Road



Serie echipament	:	5	☐ Corect
Producator	:	unknown	☐ Corect
Data fabricatiei	:	01.01.2013	☐ Corect
Capac Rezervor	:		☐ Corect
Data fabricatiei	:	12.08.2013	☐ Corect
Sistem siguranta preaplin	:	DA	☐ Corect
Data fabricatiei	:	12.08.2013	☐ Corect

Observatii:

REZERVOR 6 DIN 6

Rezervor	:	R4 monocompartmentat Adblue/Container	☐ Corect	☐ Datele sunt
corecte ☐ Necesita modificari				
Produs	:	R4 Adblue	☐ Corect	
Cod echipament	:	RO_225637	☐ Corect	
Serie echipament	:	FS	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	22.02.2019	☐ Corect	
Capac Rezervor	:	Tank shaft incl. Covers (not for AdBlue container)	☐ Corect	
Data fabricatiei	:	22.02.2019	☐ Corect	

Valori corectate / informatii de pe placuta:

Observatii:

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 3

Sistem de detectie scurgeri	:	Rezervor 1 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_225640	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	SGB	☐ Corect	
Data fabricatiei	:	12.08.2013	☐ Corect	

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 3

Sistem de detectie scurgeri	:	Rezervor 2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_225641	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	SGB	☐ Corect	
Data fabricatiei	:	12.08.2013	☐ Corect	

Observatii:

SISTEM DE DETECTIE SCURGERI 3 DIN 3

Sistem de detectie scurgeri	:	Rezervor 3 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_225642	☐ Corect	
Serie echipament	:		☐ Corect	
Producator	:	SGB	☐ Corect	
Data fabricatiei	:	12.08.2013	☐ Corect	

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____