

FISA VALIDARE INVENTAR

R1970 - Eurotruck Arad



DATE GENERALE STATIE

Cod statie	:	R1970	Data verificarii	:	
Nume statie	:	Eurotruck Arad	Persoana care verifica	:	
Numar distribuitoare	:	3			
Numar echipamente Sistem masura rezervoare	:			4	
Numar echipamente Rezervoare / sisteme asociate	:			8	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 3 - Pompa 3/4

Cod echipament	:	RO_228399	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D1813297	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantium 500T Adblue	☐ Corect	
Tip echipament	:	MPD 1/2 (Ad Blue - OMV)	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2018	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	130 l/min	☐ Corect	Observatii:
Numar pistoale	:	2	☐ Corect	
Calculator pompa	:	TQC	☐ Corect	

DISTRIBUITOR 2 DIN 3 - Pompa 5/6

Cod echipament	:	RO_228400	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D1321333	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantium 510	☐ Corect	
Tip echipament	:	HS 1-2	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	01.01.2013	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	130 l/min	☐ Corect	Observatii:
Numar pistoale	:	2	☐ Corect	
Calculator pompa	:	TQC	☐ Corect	

DISTRIBUITOR 3 DIN 3 - Pompa 1/2

Cod echipament	:	RO_237804	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	930581	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco SK700	☐ Corect	
Tip echipament	:	HS 1-2	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2022	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	130 l/min	☐ Corect	Observatii:
Numar pistoale	:	2	☐ Corect	
Calculator pompa	:	Apollo	☐ Corect	

FISA VALIDARE INVENTAR

R1970 - Eurotruck Arad



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 2

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_228402	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	ELECTRONIC_	☐ Corect	
Tip echipament	:	ELECTRONIC OPTILEVEL		
		Optilevel C104M	☐ Corect	
Data fabricatiei	:	28.01.2011	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 1

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_228403	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1 Senzori R1/1	☐ Corect	
Data fabricatiei	:	28.01.2011	☐ Corect	Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_228408	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	677	☐ Corect	
Producator	:	Mecaf_	☐ Corect	
Tip echipament	:	Rigla metalica 5m	☐ Corect	
Data fabricatiei	:	10.01.2019	☐ Corect	Observatii:

CONSOLA ATG 2 DIN 2

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_235847	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Hectronic	☐ Corect	
Tip echipament	:	Optilevel C104M	☐ Corect	
Data fabricatiei	:	25.01.2008	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1970 - Eurotruck Arad



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 2

Rezervor	:	R1/1 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_228409	☐ Corect	_____
Serie echipament	:	465	☐ Corect	_____
Producator	:	unknown	☐ Corect	_____
Data fabricatiei	:	01.01.2006	☐ Corect	Observatii:
Capac Rezervor	:	unknown	☐ Corect	_____
Data fabricatiei	:	28.01.2011	☐ Corect	_____
Sistem siguranta preaplin	:	DA	☐ Corect	_____
Data fabricatiei	:	28.01.2011	☐ Corect	_____

REZERVOR 2 DIN 2

Rezervor	:	R2 monocompartmentat Adblue/Container	☐ Corect	☐ Datele sunt
corecte ☐ Necesita modificari				
Produs	:	R2 Adblue	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_228424	☐ Corect	_____
Serie echipament	:		☐ Corect	_____
Producator	:	unknown	☐ Corect	_____
Data fabricatiei	:	28.01.2011	☐ Corect	Observatii:
Capac Rezervor	:	Tank shaft incl. Covers (not for AdBlue container)	☐ Corect	_____
Data fabricatiei	:	28.01.2011	☐ Corect	_____

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 1

Sistem de detectie scurgeri	:	Rezervor 1 monocompartmentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_228427	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:	319494	☐ Corect	_____
Producator	:	SGB	☐ Corect	_____
Data fabricatiei	:	28.01.2011	☐ Corect	Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____