

FISA VALIDARE INVENTAR

R1986 - Lugoj Ring Road



DATE GENERALE STATIE

Cod statie	:	R1986	Data verificarii	:	
Nume statie	:	Lugoj Ring Road	Persoana care verifica	:	
Numar distribuitoare	:	3			
Numar echipamente Sistem masura rezervoare	:			7	
Numar echipamente Rezervoare / sisteme asociate	:			18	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 3 - Pompa 1/2

Cod echipament	:	RO_010650	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D1534081	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantium 510	☐ Corect	
Tip echipament	:	HS 1-2	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	
Numar produse	:	1	☐ Corect	
Debit	:	130 l/min	☐ Corect	Observatii:
Numar pistoale	:	2	☐ Corect	
Calculator pompa	:	WWC	☐ Corect	

DISTRIBUITOR 2 DIN 3 - Pompa 3/4

Cod echipament	:	RO_010651	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D1534080	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantium 510	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	WWC	☐ Corect	

DISTRIBUITOR 3 DIN 3 - Pompa 5/6

Cod echipament	:	RO_010652	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	D1534079	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Tokheim_Quantium 510	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 5/6	☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	WWC	☐ Corect	

FISA VALIDARE INVENTAR

R1986 - Lugoj Ring Road



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_010654	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 350R_	☐ Corect	
Tip echipament	:	Veeder-Root 350R	☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_010655	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/1	☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_010656	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/2	☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_010657	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1	☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_010658	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/2	☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1986 - Lugoj Ring Road



VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_010659	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	17.11.2015	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_010660	☐ Corect
Serie echipament	:	899	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 5m	☐ Corect
Data fabricatiei	:	17.11.2015	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1986 - Lugoj Ring Road



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 4

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 Diesel Std	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_010661	☐ Corect	
Serie echipament	:	910	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	

REZERVOR 2 DIN 4

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 Diesel Extra	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_010664	☐ Corect	
Serie echipament	:	910	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	

REZERVOR 3 DIN 4

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 Extra 99	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_010667	☐ Corect	
Serie echipament	:	911	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	

REZERVOR 4 DIN 4

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 Standard 95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_010670	☐ Corect	
Serie echipament	:	911	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	17.11.2015	☐ Corect	

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 2

FISA VALIDARE INVENTAR

R1986 - Lugoj Ring Road



Sistem de detectie scurgeri : Rezervor 1 bicompartimentat ☐ Corect
Cod echipament : RO_010673 ☐ Corect
Serie echipament : ☐ Corect
Producator : SGB ☐ Corect
Data fabricatiei : 17.11.2015 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 2

Sistem de detectie scurgeri : Rezervor 2 bicompartimentat ☐ Corect
Cod echipament : RO_010674 ☐ Corect
Serie echipament : ☐ Corect
Producator : SGB ☐ Corect
Data fabricatiei : 17.11.2015 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____

Funcție: _____

Data: _____

Semnatura: _____