

FISA VALIDARE INVENTAR

R1997 - Timisoara 6



DATE GENERALE STATIE

Cod statie	:	R1997	Data verificarii	:	
Nume statie	:	Timisoara 6	Persoana care verifica	:	
Numar distribuitoare	:	2			
Numar echipamente Sistem masura rezervoare	:			7	
Numar echipamente Rezervoare / sisteme asociate	:			18	

FISA DE VALIDARE INVENTAR DISTRIBUITOARE

DISTRIBUITOR 1 DIN 2 - Pompa 3/4

Cod echipament	:	RO_011792	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	647658	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco SK-700	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 3/4	☐ Corect	
Data fabricatiei	:	01.01.2016	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	SK7	☐ Corect	

DISTRIBUITOR 2 DIN 2 - Pompa 1/2

Cod echipament	:	RO_011793	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Serie echipament	:	647659	☐ Corect	Valori corectate / informatii de pe placuta:
Producator	:	Gilbarco SK-700	☐ Corect	
Tip echipament	:	MPD 4/8 VR 2/4	☐ Corect	
Numar dispenser	:	Pompa 1/2	☐ Corect	
Data fabricatiei	:	01.01.2016	☐ Corect	
Numar produse	:	4	☐ Corect	
Debit	:	40 l/min	☐ Corect	Observatii:
Numar pistoale	:	8	☐ Corect	
Calculator pompa	:	SK7	☐ Corect	

FISA VALIDARE INVENTAR

R1997 - Timisoara 6



FISA DE VALIDARE INVENTAR SISTEM MASURA REZERVOARE

CONSOLA ATG 1 DIN 1

Echipament	:	Consola ATG	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_011795	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root 450R_	☐ Corect	
Tip echipament	:	Veeder-Root 450 Plus	☐ Corect	
Data fabricatiei	:	22.02.2019	☐ Corect	Observatii:

SONDA NIVEL 1 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_011796	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/1 Senzori R1	☐ Corect	
Data fabricatiei	:	22.02.2019	☐ Corect	Observatii:

SONDA NIVEL 2 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_011797	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R1/2 Senzori R2	☐ Corect	
Data fabricatiei	:	22.02.2019	☐ Corect	Observatii:

SONDA NIVEL 3 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_011798	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/1 Senzori R3/1	☐ Corect	
Data fabricatiei	:	22.02.2019	☐ Corect	Observatii:

SONDA NIVEL 4 DIN 4

Echipament	:	Sonda nivel	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Cod echipament	:	RO_011799	☐ Corect	Valori corectate / informatii de pe placuta:
Serie echipament	:		☐ Corect	
Producator	:	Veeder-Root_	☐ Corect	
Tip echipament	:	Sonda R2/2 Senzori R3/2	☐ Corect	
Data fabricatiei	:	22.02.2019	☐ Corect	Observatii:

FISA VALIDARE INVENTAR

R1997 - Timisoara 6



VAS ETALON 1 DIN 1

Echipament	:	Vas Etalon	☐ Corect
Cod echipament	:	RO_011800	☐ Corect
Serie echipament	:		☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Vas etalon	☐ Corect
Data fabricatiei	:	15.07.2016	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

RIGLA GRADATA 1 DIN 1

Echipament	:	Rigla Gradata	☐ Corect
Cod echipament	:	RO_011801	☐ Corect
Serie echipament	:	498	☐ Corect
Producator	:	Mecaf_	☐ Corect
Tip echipament	:	Rigla metalica Rigla 4m	☐ Corect
Data fabricatiei	:	23.01.2020	☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

FISA VALIDARE INVENTAR

R1997 - Timisoara 6



FISA DE VALIDARE INVENTAR REZERVOARE

REZERVOARE

REZERVOR 1 DIN 4

Rezervor	:	R1/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/1 OMV Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_011802	☐ Corect	
Serie echipament	:	726	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	15.07.2016	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	15.07.2016	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	15.07.2016	☐ Corect	

REZERVOR 2 DIN 4

Rezervor	:	R1/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R1/2 MM Diesel	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_011805	☐ Corect	
Serie echipament	:	726	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	15.07.2016	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	15.07.2016	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	15.07.2016	☐ Corect	

REZERVOR 3 DIN 4

Rezervor	:	R2/1 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/1 MM100	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_011808	☐ Corect	
Serie echipament	:	725	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	01.01.2015	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	15.07.2016	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	15.07.2016	☐ Corect	

REZERVOR 4 DIN 4

Rezervor	:	R2/2 bicompartimentat	☐ Corect	☐ Datele sunt corecte ☐ Necesita modificari
Produs	:	R2/2 MM95	☐ Corect	Valori corectate / informatii de pe placuta:
Cod echipament	:	RO_011811	☐ Corect	
Serie echipament	:	725	☐ Corect	
Producator	:	unknown	☐ Corect	
Data fabricatiei	:	15.07.2016	☐ Corect	Observatii:
Capac Rezervor	:		☐ Corect	
Data fabricatiei	:	15.07.2016	☐ Corect	
Sistem siguranta preaplin	:	DA	☐ Corect	
Data fabricatiei	:	15.07.2016	☐ Corect	

DETECTIE SCURGERI

SISTEM DE DETECTIE SCURGERI 1 DIN 2

FISA VALIDARE INVENTAR

R1997 - Timisoara 6



Sistem de detectie scurgeri : Rezervor 1 bicompartimentat ☐ Corect
Cod echipament : RO_011814 ☐ Corect
Serie echipament : ☐ Corect
Producator : SGB ☐ Corect
Data fabricatiei : 15.07.2016 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

SISTEM DE DETECTIE SCURGERI 2 DIN 2

Sistem de detectie scurgeri : Rezervor 2 bicompartimentat ☐ Corect
Cod echipament : RO_011815 ☐ Corect
Serie echipament : ☐ Corect
Producator : SGB ☐ Corect
Data fabricatiei : 15.07.2016 ☐ Corect

☐ Datele sunt corecte ☐ Necesita modificari

Valori corectate / informatii de pe placuta:

Observatii:

VERIFICARE FINALA

Nume: _____
Functie: _____
Data: _____
Semnatura: _____